

NC School District/430 Harnett County/High School

Triton High

Final

Campus Assessment Report

March 11, 2017



Table of Contents

Campus Executive Summary	7
Campus Dashboard Summary	10
Campus Condition Summary	11
<u>1985 Main Building</u>	13
Executive Summary	13
Dashboard Summary	14
Condition Summary	15
Photo Album	16
Condition Detail	17
System Listing	18
System Notes	20
Renewal Schedule	34
Forecasted Sustainment Requirement	37
Deficiency Summary By System	38
Deficiency Summary By Priority	39
Deficiency By Priority Investment	40
Deficiency Summary By Category	41
Deficiency Details By Priority	42
<u>1986 Baseball Pressbox</u>	52
Executive Summary	52
Dashboard Summary	53
Condition Summary	54
Photo Album	55
Condition Detail	56
System Listing	57
System Notes	58
Renewal Schedule	65
Forecasted Sustainment Requirement	67
Deficiency Summary By System	68

Campus Assessment Report

Deficiency Summary By Priority	69
Deficiency By Priority Investment	70
Deficiency Summary By Category	71
Deficiency Details By Priority	72
<u>1986 Concession</u>	73
Executive Summary	73
Dashboard Summary	74
Condition Summary	75
Photo Album	76
Condition Detail	77
System Listing	78
System Notes	79
Renewal Schedule	86
Forecasted Sustainment Requirement	88
Deficiency Summary By System	89
Deficiency Summary By Priority	90
Deficiency By Priority Investment	91
Deficiency Summary By Category	92
Deficiency Details By Priority	93
<u>1986 Football Fieldhouse</u>	95
Executive Summary	95
Dashboard Summary	96
Condition Summary	97
Photo Album	98
Condition Detail	99
System Listing	100
System Notes	101
Renewal Schedule	108
Forecasted Sustainment Requirement	110
Deficiency Summary By System	111
Deficiency Summary By Priority	112

Campus Assessment Report

Deficiency By Priority Investment	113
Deficiency Summary By Category	114
Deficiency Details By Priority	115
<u>1986 Pressbox</u>	117
Executive Summary	117
Dashboard Summary	118
Condition Summary	119
Photo Album	120
Condition Detail	121
System Listing	122
System Notes	123
Renewal Schedule	128
Forecasted Sustainment Requirement	130
Deficiency Summary By System	131
Deficiency Summary By Priority	132
Deficiency By Priority Investment	133
Deficiency Summary By Category	134
Deficiency Details By Priority	135
<u>1986 Softball Concession</u>	136
Executive Summary	136
Dashboard Summary	137
Condition Summary	138
Photo Album	139
Condition Detail	140
System Listing	141
System Notes	142
Renewal Schedule	148
Forecasted Sustainment Requirement	150
Deficiency Summary By System	151
Deficiency Summary By Priority	152
Deficiency By Priority Investment	153

Campus Assessment Report

Deficiency Summary By Category	154
Deficiency Details By Priority	155
<u>1986 Tractor Building</u>	156
Executive Summary	156
Dashboard Summary	157
Condition Summary	158
Photo Album	159
Condition Detail	160
System Listing	161
System Notes	162
Renewal Schedule	164
Forecasted Sustainment Requirement	165
Deficiency Summary By System	166
Deficiency Summary By Priority	167
Deficiency By Priority Investment	168
Deficiency Summary By Category	169
Deficiency Details By Priority	170
<u>2002 Metal Building</u>	171
Executive Summary	171
Dashboard Summary	172
Condition Summary	173
Photo Album	174
Condition Detail	175
System Listing	176
System Notes	177
Renewal Schedule	181
Forecasted Sustainment Requirement	184
Deficiency Summary By System	185
Deficiency Summary By Priority	186
Deficiency By Priority Investment	187
Deficiency Summary By Category	188

Campus Assessment Report

Deficiency Details By Priority	189
<u>Site</u>	190
Executive Summary	190
Dashboard Summary	191
Condition Summary	192
Photo Album	193
Condition Detail	194
System Listing	195
System Notes	196
Renewal Schedule	202
Forecasted Sustainment Requirement	203
Deficiency Summary By System	204
Deficiency Summary By Priority	205
Deficiency By Priority Investment	206
Deficiency Summary By Category	207
Deficiency Details By Priority	208

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	254,932
Year Built:	1985
Last Renovation:	
Replacement Value:	\$59,874,250
Repair Cost:	\$14,541,595.27
Total FCI:	24.29 %
Total RSLI:	31.87 %
FCA Score:	75.71



Description:

GENERAL:

Triton High School is located at 215 Maynard Lake Road in Erwin, North Carolina. The 2 story, 246,550 square foot building was originally constructed in 1985. There have been no additions or renovations to the building.

SITE:

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, football field, baseball field, softball field, and fencing. Site mechanical and electrical features include water, sewer, propane and natural gas, and site lighting. This report contains condition and adequacy data collected during the 2016 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site features.

STRUCTURAL/EXTERIOR CLOSURE:

Campus Assessment Report - Triton High

The building rests on footings and foundation walls. The building does not have a basement. The superstructure is steel frame. Floor construction is slab on-grade. Roof construction is steel. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with operable panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is typically low slope thermos plastic roof. Most building entrances appear to comply with ADA requirements.

INTERIORS:

Interior construction partition wall types include painted CMU and painted drywalls. Interior doors are generally solid core wood with hollow steel frames and mostly without glazing. Interior fittings include the following items: chalk and tack boards, graphics and identifying devices, lockers, toilet accessories, storage shelving, handrails, fabricated toilet partitions. Stair construction includes steel risers and concrete treads with concrete finishes and a wooden staircase. The interior wall finishes are typically paint. Floor finishes in common areas are typically terrazzo. Floor finishes in assignable spaces is typically vinyl composition tile, carpet, wood, and tiles. Ceiling finishes in common areas are typically suspended acoustical tile. Ceiling finishes in assignable areas are typically painted drywall.

CONVEYING:

The building does include conveying equipment. Conveying equipment includes 1 hydraulic elevators.

PLUMBING:

Domestic water distribution is galvanized steel with gas hot water heating. Sanitary waste system is cast iron. Rain water drainage system is internal with roof drains.

HVAC:

Heating is provided by 2, gas fired boilers . Cooling is supplied by 2, water cooled chillers. The heating/cooling distribution system is a ductwork system utilizing air handling units. Fresh air is supplied by air handling units. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are digital and are centrally controlled by an energy management system. This building does not have a remote Building Automation System.

FIRE PROTECTION:

The building does not have a fire sprinkler system for the majority of the building, only the Automotive Classroom in the vocational building has a sprinkler system. The building does not have additional fire suppression systems. Standpipes are not included within fire stairs. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer, owned and maintained by the local utility company through a main switchboard/distribution panel located in the building. Lighting is lay-in, recessed and surface type, fluorescent light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in common spaces, balconies and interior corridors. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building does not include an internal security system. The building does not have controlled entry doors access. The security system has CCTV cameras and is centrally monitored; this building has a public address and paging system combined with the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does have a separately derived emergency power system. It is provided by 1, emergency generator.

E. EQUIPMENT & FURNISHINGS:

This building does include the following items and equipment: fixed food service, library equipment, theater and stage, audio-visual, detention, laboratory, fixed casework, window treatment, and multiple seating furnishings.

Campus Assessment Report - Triton High

Attributes:

General Attributes:

Condition Assessor: Somnath Das Assessment Date:
Suitability Assessor:





School Information:

HS Attendance Area:	Harnett - Triton HS	LEA School No.:	430-378
No. of Mobile Units:	7	No. of Bldgs.:	8
SF of Mobile Units:	6048	Status:	Active
School Grades:	9-12	Site Acreage:	77.9

Campus Dashboard Summary

Gross Area: 254,932
 Year Built: 1985
 Repair Cost: \$14,541,595
 FCI: 24.29 %

Last Renovation:
 Replacement Value: \$59,874,250
 RSLI%: 31.87 %



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Unifomat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	68.73 %	0.00 %	\$0.00
A20 - Basement Construction	68.00 %	0.00 %	\$0.00
B10 - Superstructure	68.12 %	0.00 %	\$0.00
B20 - Exterior Enclosure	36.06 %	0.25 %	\$14,834.00
B30 - Roofing	57.08 %	110.66 %	\$1,408,960.36
C10 - Interior Construction	34.31 %	31.84 %	\$709,386.56
C20 - Stairs	68.01 %	0.00 %	\$0.00
C30 - Interior Finishes	13.51 %	50.02 %	\$3,084,169.53
D10 - Conveying	0.00 %	110.00 %	\$265,781.00
D20 - Plumbing	12.74 %	5.87 %	\$205,989.00
D30 - HVAC	27.30 %	59.19 %	\$4,550,171.00
D40 - Fire Protection	13.33 %	2,353.25 %	\$1,276,450.82
D50 - Electrical	20.41 %	2.63 %	\$181,707.00
E10 - Equipment	22.76 %	24.95 %	\$1,482,453.00
E20 - Furnishings	19.59 %	2.34 %	\$29,673.00
G20 - Site Improvements	32.47 %	13.88 %	\$891,752.00
G30 - Site Mechanical Utilities	34.29 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	22.76 %	35.32 %	\$440,268.00
Totals:	31.87 %	24.29 %	\$14,541,595.27

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
1985 Main Building	246,550	26.97	\$26,400.00	\$2,863,925.00	\$8,831,629.26	\$1,276,450.82	\$0.00
1986 Baseball Pressbox	750	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
1986 Concession	1,100	27.03	\$0.00	\$0.00	\$45,473.19	\$0.00	\$0.00
1986 Football Fieldhouse	3,200	20.42	\$0.00	\$0.00	\$155,092.00	\$0.00	\$0.00
1986 Pressbox	250	8.36	\$0.00	\$0.00	\$4,295.00	\$0.00	\$0.00
1986 Softball Concession	550	8.21	\$0.00	\$0.00	\$6,310.00	\$0.00	\$0.00
1986 Tractor Building	900	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2002 Metal Building	1,632	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Site	254,932	13.15	\$555,242.00	\$0.00	\$776,778.00	\$0.00	\$0.00
Total:		24.29	\$581,642.00	\$2,863,925.00	\$9,819,577.45	\$1,276,450.82	\$0.00

Deficiencies By Priority



Budget Estimate Total: \$14,541,595.27

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	246,550
Year Built:	1985
Last Renovation:	
Replacement Value:	\$48,201,216
Repair Cost:	\$12,998,405.08
Total FCI:	26.97 %
Total RSLI:	31.60 %
FCA Score:	73.03







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	246,550
Year Built:	1985	Last Renovation:	
Repair Cost:	\$12,998,405	Replacement Value:	\$48,201,216
FCI:	26.97 %	RSLI%:	31.60 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	68.00 %	0.00 %	\$0.00
A20 - Basement Construction	68.00 %	0.00 %	\$0.00
B10 - Superstructure	68.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	34.88 %	0.24 %	\$13,200.00
B30 - Roofing	58.14 %	114.78 %	\$1,407,236.36
C10 - Interior Construction	34.69 %	33.38 %	\$709,386.56
C20 - Stairs	68.00 %	0.00 %	\$0.00
C30 - Interior Finishes	13.35 %	50.47 %	\$2,993,713.34
D10 - Conveying	0.00 %	110.00 %	\$265,781.00
D20 - Plumbing	12.80 %	5.01 %	\$170,859.00
D30 - HVAC	27.45 %	59.84 %	\$4,526,412.00
D40 - Fire Protection	13.33 %	2,353.25 %	\$1,276,450.82
D50 - Electrical	20.38 %	2.67 %	\$181,707.00
E10 - Equipment	22.86 %	24.59 %	\$1,453,659.00
E20 - Furnishings	20.00 %	0.00 %	\$0.00
Totals:	31.60 %	26.97 %	\$12,998,405.08

Photo Album

The photo album consists of the various cardinal directions of the building..

1). Southwest Elevation - Dec 05, 2016



2). West Elevation - Dec 05, 2016



3). East Elevation - Dec 05, 2016



4). South Elevation - Dec 05, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

Campus Assessment Report - 1985 Main Building

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$2.18	S.F.	246,550	100	1985	2085		68.00 %	0.00 %	68			\$537,479
A1030	Slab on Grade	\$4.08	S.F.	246,550	100	1985	2085		68.00 %	0.00 %	68			\$1,005,924
A2010	Basement Excavation	\$0.83	S.F.	246,550	100	1985	2085		68.00 %	0.00 %	68			\$204,637
A2020	Basement Walls	\$5.74	S.F.	246,550	100	1985	2085		68.00 %	0.00 %	68			\$1,415,197
B1010	Floor Construction	\$11.42	S.F.	246,550	100	1985	2085		68.00 %	0.00 %	68			\$2,815,601
B1020	Roof Construction	\$7.60	S.F.	246,550	100	1985	2085		68.00 %	0.00 %	68			\$1,873,780
B2010	Exterior Walls	\$8.84	S.F.	246,550	100	1985	2085		68.00 %	0.61 %	68		\$13,200.00	\$2,179,502
B2020	Exterior Windows	\$12.78	S.F.	246,550	30	1985	2015	2021	13.33 %	0.00 %	4			\$3,150,909
B2030	Exterior Doors	\$0.81	S.F.	246,550	30	1985	2015	2021	13.33 %	0.00 %	4			\$199,706
B3010120	Single Ply Membrane	\$6.98	S.F.	168,232	20	2009	2029		60.00 %	119.32 %	12		\$1,401,109.05	\$1,174,259
B3020	Roof Openings	\$0.21	S.F.	246,550	25	1985	2010	2021	16.00 %	11.83 %	4		\$6,127.31	\$51,776
C1010	Partitions	\$4.70	S.F.	246,550	75	1985	2060		57.33 %	1.14 %	43		\$13,200.00	\$1,158,785
C1020	Interior Doors	\$2.44	S.F.	246,550	30	1985	2015		0.00 %	110.00 %	-2		\$661,740.00	\$601,582
C1030	Fittings	\$1.48	S.F.	246,550	20	1985	2005	2021	20.00 %	9.44 %	4		\$34,446.56	\$364,894
C2010	Stair Construction	\$1.29	S.F.	246,550	100	1985	2085		68.00 %	0.00 %	68			\$318,050
C3010	Wall Finishes	\$2.56	S.F.	246,550	10	1985	1995	2021	40.00 %	0.00 %	4			\$631,168
C3020	Floor Finishes	\$10.94	S.F.	246,550	20	1985	2005	2021	20.00 %	4.81 %	4		\$129,788.34	\$2,697,257
C3030	Ceiling Finishes	\$10.56	S.F.	246,550	25	1985	2010		0.00 %	110.00 %	-7		\$2,863,925.00	\$2,603,568
D1010	Elevators and Lifts	\$0.98	S.F.	246,550	30	1985	2015		0.00 %	110.00 %	-2		\$265,781.00	\$241,619
D2010	Plumbing Fixtures	\$8.83	S.F.	246,550	30	1985	2015	2021	13.33 %	0.00 %	4			\$2,177,037
D2020	Domestic Water Distribution	\$1.64	S.F.	246,550	30	1985	2015	2021	13.33 %	0.00 %	4			\$404,342
D2030	Sanitary Waste	\$2.59	S.F.	246,550	30	1985	2015	2021	13.33 %	0.00 %	4			\$638,565
D2040	Rain Water Drainage	\$0.63	S.F.	246,550	30	1985	2015		0.00 %	110.00 %	-2		\$170,859.00	\$155,327
D2090	Other Plumbing Systems -Nat Gas	\$0.15	S.F.	246,550	40	1985	2025		20.00 %	0.00 %	8			\$36,983
D3020	Heat Generating Systems	\$6.93	S.F.	246,550	30	1985	2015		0.00 %	110.00 %	-2		\$1,879,451.00	\$1,708,592
D3030	Cooling Generating Systems	\$7.18	S.F.	246,550	25	2011	2036		76.00 %	0.00 %	19			\$1,770,229
D3040	Distribution Systems	\$8.37	S.F.	246,550	30	1985	2015		0.00 %	110.00 %	-2		\$2,269,986.00	\$2,063,624
D3050	Terminal & Package Units	\$4.16	S.F.	246,550	15	1985	2000	2021	26.67 %	0.00 %	4			\$1,025,648
D3060	Controls & Instrumentation	\$2.65	S.F.	246,550	20	2011	2031		70.00 %	0.00 %	14			\$653,358
D3090	Other HVAC Systems/Equip	\$1.39	S.F.	246,550	20	1985	2005		0.00 %	110.00 %	-12		\$376,975.00	\$342,705
D4010	Sprinklers	\$0.13	S.F.	246,550	30	1985	2015	2021	13.33 %	3,982.44 %	4		\$1,276,450.82	\$32,052
D4020	Standpipes	\$0.09	S.F.	246,550	30	1985	2015	2021	13.33 %	0.00 %	4			\$22,190
D5010	Electrical Service/Distribution	\$1.60	S.F.	246,550	40	1985	2025		20.00 %	0.00 %	8			\$394,480


Campus Assessment Report - 1985 Main Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
D5020	Branch Wiring	\$4.55	S.F.	246,550	30	1985	2015	2021	13.33 %	0.00 %	4			\$1,121,803
D5020	Lighting	\$10.64	S.F.	246,550	30	1985	2015	2021	13.33 %	0.00 %	4			\$2,623,292
D5030810	Security & Detection Systems	\$1.97	S.F.	246,550	15	2014	2029		80.00 %	0.00 %	12			\$485,704
D5030910	Fire Alarm Systems	\$3.56	S.F.	246,550	15	2004	2019		13.33 %	0.00 %	2			\$877,718
D5030920	Data Communication	\$4.61	S.F.	246,550	15	1985	2000	2021	26.67 %	0.00 %	4			\$1,136,596
D5090	Other Electrical Systems	\$0.67	S.F.	246,550	20	1985	2005		0.00 %	110.00 %	-12		\$181,707.00	\$165,189
E1010	Commercial Equipment	\$4.34	S.F.	246,550	20	1985	2005	2021	20.00 %	0.00 %	4			\$1,070,027
E1020	Institutional Equipment	\$11.77	S.F.	246,550	20	1985	2005	2021	20.00 %	0.00 %	4			\$2,901,894
E1030	Vehicular Equipment	\$2.51	S.F.	246,550	20	2015	2035		90.00 %	0.00 %	18			\$618,841
E1090	Other Equipment	\$5.36	S.F.	246,550	20	1985	2005		0.00 %	110.00 %	-12		\$1,453,659.00	\$1,321,508
E2010	Fixed Furnishings	\$4.98	S.F.	246,550	20	1985	2005	2021	20.00 %	0.00 %	4			\$1,227,819
Total									31.60 %	26.97 %			\$12,998,405.08	\$48,201,216

System Notes


The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

Campus Assessment Report - 1985 Main Building

System: B2030 - Exterior Doors




Note:

System: B3010120 - Single Ply Membrane



Note: Standing water issues, roof is not properly graded.


System: B3020 - Roof Openings



Note: The roof hatches are beyond their service life and need to be replaced. 3

Campus Assessment Report - 1985 Main Building

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note: The interior doors are beyond their service life and should be replaced.


System: C1030 - Fittings



Note:




Campus Assessment Report - 1985 Main Building

System: C2010 - Stair Construction



Note:


System: C3010 - Wall Finishes



Note:

Campus Assessment Report - 1985 Main Building

System: C3020 - Floor Finishes




Note: The carpet is beyond its service life and should be replaced.

System: C3030 - Ceiling Finishes



Note:

System: D1010 - Elevators and Lifts



Note:

Campus Assessment Report - 1985 Main Building

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

Campus Assessment Report - 1985 Main Building

System: D2040 - Rain Water Drainage



Note: The rain water drainage system is beyond its service life and should be replaced.

System: D2090 - Other Plumbing Systems -Nat Gas



Note:

System: D3020 - Heat Generating Systems



Note: The natural gas boilers are beyond their service life and should be replaced.

Campus Assessment Report - 1985 Main Building

System: D3030 - Cooling Generating Systems



Note: 2 chillers 2012

System: D3040 - Distribution Systems



Note: The rooftop units are beyond their service life and should be replaced.


System: D3050 - Terminal & Package Units



Note:

Campus Assessment Report - 1985 Main Building

System: D3060 - Controls & Instrumentation



Note:

System: D3090 - Other HVAC Systems/Equip



Note:


Campus Assessment Report - 1985 Main Building

System: D4010 - Sprinklers



Note:

System: D4020 - Standpipes



Note:

System: D5010 - Electrical Service/Distribution



Note: 3000 amps



Campus Assessment Report - 1985 Main Building

System: D5020 - Branch Wiring




Note:

System: D5020 - Lighting



Note:


System: D5030810 - Security & Detection Systems



Note:

Campus Assessment Report - 1985 Main Building

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

System: D5090 - Other Electrical Systems



Note: The generator system is beyond its service life and should be replaced.



Campus Assessment Report - 1985 Main Building

System: E1010 - Commercial Equipment





Note:

System: E1020 - Institutional Equipment



Note:

System: E1030 - Vehicular Equipment



Note:

Campus Assessment Report - 1985 Main Building

System: E1090 - Other Equipment



Note: The kitchen equipment is beyond its service life and should be replaced.

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$12,998,405	\$0	\$1,024,288	\$0	\$26,589,772	\$0	\$0	\$0	\$601,220	\$0	\$0	\$41,213,686
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$13,200	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,200
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$3,901,014	\$0	\$0	\$0	\$0	\$0	\$0	\$3,901,014
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$247,247	\$0	\$0	\$0	\$0	\$0	\$0	\$247,247
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$1,401,109	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,401,109
B3020 - Roof Openings	\$6,127	\$0	\$0	\$0	\$64,101	\$0	\$0	\$0	\$0	\$0	\$0	\$70,228
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$13,200	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,200
C1020 - Interior Doors	\$661,740	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$661,740
C1030 - Fittings	\$34,447	\$0	\$0	\$0	\$451,760	\$0	\$0	\$0	\$0	\$0	\$0	\$486,207
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

Campus Assessment Report - 1985 Main Building

* C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$781,424	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$781,424
C3020 - Floor Finishes	\$129,788	\$0	\$0	\$0	\$3,339,366	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,469,154
C3030 - Ceiling Finishes	\$2,863,925	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,863,925
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$265,781	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$265,781
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$2,695,301	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,695,301
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$500,599	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$500,599
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$790,581	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$790,581
D2040 - Rain Water Drainage	\$170,859	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$170,859
D2090 - Other Plumbing Systems -Nat Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$51,533	\$0	\$0	\$0	\$51,533
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$1,879,451	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,879,451
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$2,269,986	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,269,986
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$1,269,814	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,269,814
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3090 - Other HVAC Systems/Equip	\$376,975	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$376,975
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$1,276,451	\$0	\$0	\$0	\$39,682	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,316,133
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$27,471	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$27,471
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$549,687	\$0	\$0	\$0	\$549,687
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$1,388,859	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,388,859
D5020 - Lighting	\$0	\$0	\$0	\$0	\$3,247,792	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,247,792
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$0	\$0	\$1,024,288	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,024,288
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$1,407,173	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,407,173
D5090 - Other Electrical Systems	\$181,707	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$181,707


Campus Assessment Report - 1985 Main Building

E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$1,324,758	\$0	\$0	\$0	\$0	\$0	\$0	\$1,324,758
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$3,592,718	\$0	\$0	\$0	\$0	\$0	\$0	\$3,592,718
E1030 - Vehicular Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$1,453,659	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,453,659
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$1,520,113	\$0	\$0	\$0	\$0	\$0	\$0	\$1,520,113

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$12,998,405.08

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$12,998,405.08


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2010	Exterior Walls	\$13,200.00	\$0.00	\$0.00	\$0.00	\$0.00	\$13,200.00
B3010120	Single Ply Membrane	\$0.00	\$0.00	\$1,401,109.05	\$0.00	\$0.00	\$1,401,109.05
B3020	Roof Openings	\$0.00	\$0.00	\$6,127.31	\$0.00	\$0.00	\$6,127.31
C1010	Partitions	\$13,200.00	\$0.00	\$0.00	\$0.00	\$0.00	\$13,200.00
C1020	Interior Doors	\$0.00	\$0.00	\$661,740.00	\$0.00	\$0.00	\$661,740.00
C1030	Fittings	\$0.00	\$0.00	\$34,446.56	\$0.00	\$0.00	\$34,446.56
C3020	Floor Finishes	\$0.00	\$0.00	\$129,788.34	\$0.00	\$0.00	\$129,788.34
C3030	Ceiling Finishes	\$0.00	\$2,863,925.00	\$0.00	\$0.00	\$0.00	\$2,863,925.00
D1010	Elevators and Lifts	\$0.00	\$0.00	\$265,781.00	\$0.00	\$0.00	\$265,781.00
D2040	Rain Water Drainage	\$0.00	\$0.00	\$170,859.00	\$0.00	\$0.00	\$170,859.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$1,879,451.00	\$0.00	\$0.00	\$1,879,451.00
D3040	Distribution Systems	\$0.00	\$0.00	\$2,269,986.00	\$0.00	\$0.00	\$2,269,986.00
D3090	Other HVAC Systems/Equip	\$0.00	\$0.00	\$376,975.00	\$0.00	\$0.00	\$376,975.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$1,276,450.82	\$0.00	\$1,276,450.82
D5090	Other Electrical Systems	\$0.00	\$0.00	\$181,707.00	\$0.00	\$0.00	\$181,707.00
E1090	Other Equipment	\$0.00	\$0.00	\$1,453,659.00	\$0.00	\$0.00	\$1,453,659.00
	Total:	\$26,400.00	\$2,863,925.00	\$8,831,629.26	\$1,276,450.82	\$0.00	\$12,998,405.08

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:




Budget Estimate Total: \$12,998,405.08

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Currently Critical (Immediate):


System: B2010 - Exterior Walls



Location: Exterior of the building
Distress: Failing
Category: Safety / Building Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Engineering Study-2016-11-15 17:41:59
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$13,200.00
Assessor Name: Eduardo Lopez
Date Created: 12/06/2016

Notes: There are various places where visible cracks are showing, and then there are other areas where the bricks and mortar are missing.

System: C1010 - Partitions



Location: Library 2nd Floor and 1st floor classroom 318
Distress: Failing
Category: Safety / Building Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Engineering Study
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$13,200.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: There are visible cracks on the partition wall which should be studied by a professional engineer.

Priority 2 - Potentially Critical (Year 1):

System: C3030 - Ceiling Finishes



Location: Throughout Building
Distress: Failing
Category: Deferred Maintenance / Building Code Compliance
Priority: 2 - Potentially Critical (Year 1)
Correction: Renew System
Qty: 246,550.00
Unit of Measure: S.F.
Estimate: \$2,863,925.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The ceiling finishes are in poor condition, most of the areas near the gymnasium, auditorium, and cafeteria are showing signs of high humidity. Some of the ceiling tiles has mold, some of them are broken and the rest of them are sagging. The ceiling tiles need to be replaced.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B3010120 - Single Ply Membrane



Location: Roof
Distress: Failing
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Minor replacement, 25% of roof area, thermoset
Qty: 2,105.00
Unit of Measure: Sq.
Estimate: \$1,401,109.05
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The roof is not graded properly and thus creating issues for water drainage.

System: B3020 - Roof Openings



Location: Roof
Distress: Beyond Service Life
Category: Deferred Maintenance / Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace roof hatch and structure single unit
Qty: 3.00
Unit of Measure: Ea.
Estimate: \$6,127.31
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The roof hatches are rusted and beyond their service life and need to be replaced with OSHA compliant access hatches.

System: C1020 - Interior Doors



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 246,550.00
Unit of Measure: S.F.
Estimate: \$661,740.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The interior doors are beyond their service life and should be replaced.

System: C1030 - Fittings



Location: Throughout the building
Distress: Inadequate
Category: Deferred Maintenance / Accessibility Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace signage and toilet partitions
Qty: 325.00
Unit of Measure: Ea.
Estimate: \$34,446.56
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The signages are not ADA code compliant and they should be replaced.

System: C3020 - Floor Finishes



Location: Second floor
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace vinyl tile flooring
Qty: 750.00
Unit of Measure: S.Y.
Estimate: \$80,635.50
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The vinyl tiles are in poor condition and beyond their service life and should be replaced.

System: C3020 - Floor Finishes



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace carpet
Qty: 575.00
Unit of Measure: S.Y.
Estimate: \$49,152.84
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The carpet is beyond its service life and should be replaced.

System: D1010 - Elevators and Lifts



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 246,550.00
Unit of Measure: S.F.
Estimate: \$265,781.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The elevator system is beyond its service life and should be replaced.

System: D2040 - Rain Water Drainage



Location: Roof
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 246,550.00
Unit of Measure: S.F.
Estimate: \$170,859.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The rain water drainage system is beyond its service life and should be replaced.

System: D3020 - Heat Generating Systems



Location: Mechanical Room
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 246,550.00
Unit of Measure: S.F.
Estimate: \$1,879,451.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The natural gas boilers are beyond their service life and should be replaced.

System: D3040 - Distribution Systems



Location: Roof
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 246,550.00
Unit of Measure: S.F.
Estimate: \$2,269,986.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The rooftop units and the older air handling units are beyond their service life and should be replaced.

System: D3090 - Other HVAC Systems/Equip



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 246,550.00
Unit of Measure: S.F.
Estimate: \$376,975.00
Assessor Name: Eduardo Lopez
Date Created: 12/05/2016

Notes: The fumehoods, dust collectors, and welding exhaust are beyond their service life and should be replaced.

System: D5090 - Other Electrical Systems



Location: Mechanical Room
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 246,550.00
Unit of Measure: S.F.
Estimate: \$181,707.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The generator system is beyond its service life and should be replaced.

System: E1090 - Other Equipment



Location: Cafeteria
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 246,550.00
Unit of Measure: S.F.
Estimate: \$1,453,659.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The kitchen equipment is beyond its service life and should be replaced.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Safety / Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Install Sprinkler System
Qty: 185,765.00
Unit of Measure: S.F.
Estimate: \$1,276,450.82
Assessor Name: Eduardo Lopez
Date Created: 12/07/2016

Notes: The building is missing a sprinkler system and it should be added to the building.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	750
Year Built:	1986
Last Renovation:	
Replacement Value:	\$171,719
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	40.06 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.


Dashboard Summary

Function:	HS -High School	Gross Area:	750
Year Built:	1986	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$171,719
FCI:	0.00 %	RSLI%:	40.06 %

No data found for this asset

No data found for this asset

No data found for this asset



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	69.00 %	0.00 %	\$0.00
B10 - Superstructure	69.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	43.15 %	0.00 %	\$0.00
B30 - Roofing	20.00 %	0.00 %	\$0.00
C10 - Interior Construction	20.05 %	0.00 %	\$0.00
C20 - Stairs	69.00 %	0.00 %	\$0.00
C30 - Interior Finishes	22.38 %	0.00 %	\$0.00
D20 - Plumbing	13.33 %	0.00 %	\$0.00
D30 - HVAC	13.33 %	0.00 %	\$0.00
D50 - Electrical	14.69 %	0.00 %	\$0.00
E20 - Furnishings	20.00 %	0.00 %	\$0.00
Totals:	40.07 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Dec 06, 2016



2). Northeast Elevation - Dec 06, 2016



3). North Elevation - Dec 06, 2016



4). West Elevation - Dec 06, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	750	100	1986	2086		69.00 %	0.00 %	69			\$15,098
A1030	Slab on Grade	\$19.75	S.F.	750	100	1986	2086		69.00 %	0.00 %	69			\$14,813
B1010	Floor Construction	\$11.44	S.F.	750	100	1986	2086		69.00 %	0.00 %	69			\$8,580
B1020	Roof Construction	\$16.26	S.F.	750	100	1986	2086		69.00 %	0.00 %	69			\$12,195
B2010	Exterior Walls	\$29.79	S.F.	750	100	1986	2086		69.00 %	0.00 %	69			\$22,343
B2020	Exterior Windows	\$17.17	S.F.	750	30	1986	2016	2021	13.33 %	0.00 %	4			\$12,878
B2030	Exterior Doors	\$8.66	S.F.	750	30	1986	2016	2021	13.33 %	0.00 %	4			\$6,495
B3010140	Asphalt Shingles	\$4.32	S.F.	750	20	1986	2006	2021	20.00 %	0.00 %	4			\$3,240
C1010	Partitions	\$6.22	S.F.	750	40	1986	2026		22.50 %	0.00 %	9			\$4,665
C1020	Interior Doors	\$2.20	S.F.	750	30	1986	2016	2021	13.33 %	0.00 %	4			\$1,650
C1030	Fittings	\$8.47	S.F.	750	20	1986	2006	2021	20.00 %	0.00 %	4			\$6,353
C2010	Stair Construction	\$1.77	S.F.	1,632	100	1986	2086		69.00 %	0.00 %	69			\$2,889
C3010	Wall Finishes	\$5.11	S.F.	750	10	1986	1996	2021	40.00 %	0.00 %	4			\$3,833
C3020	Floor Finishes	\$12.37	S.F.	750	20	1986	2006	2021	20.00 %	0.00 %	4			\$9,278
C3030	Ceiling Finishes	\$9.52	S.F.	750	25	1986	2011	2021	16.00 %	0.00 %	4			\$7,140
D2010	Plumbing Fixtures	\$9.98	S.F.	750	30	1986	2016	2021	13.33 %	0.00 %	4			\$7,485
D2020	Domestic Water Distribution	\$0.84	S.F.	750	30	1986	2016	2021	13.33 %	0.00 %	4			\$630
D2030	Sanitary Waste	\$5.94	S.F.	750	30	1986	2016	2021	13.33 %	0.00 %	4			\$4,455
D3040	Distribution Systems	\$5.35	S.F.	750	30	1986	2016	2021	13.33 %	0.00 %	4			\$4,013
D5010	Electrical Service/Distribution	\$3.09	S.F.	750	40	1986	2026		22.50 %	0.00 %	9			\$2,318
D5020	Branch Wiring	\$9.24	S.F.	750	30	1986	2016	2021	13.33 %	0.00 %	4			\$6,930
D5020	Lighting	\$8.58	S.F.	750	30	1986	2016	2021	13.33 %	0.00 %	4			\$6,435
E2010	Fixed Furnishings	\$10.67	S.F.	750	20	1986	2006	2021	20.00 %	0.00 %	4			\$8,003
Total									40.07 %					\$171,719

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:



Campus Assessment Report - 1986 Baseball Pressbox

System: B3010140 - Asphalt Shingles






Note:

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note:


Campus Assessment Report - 1986 Baseball Pressbox

System: C1030 - Fittings




Note:

System: C2010 - Stair Construction



Note:


System: C3010 - Wall Finishes



Note:

Campus Assessment Report - 1986 Baseball Pressbox

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:



System: D2010 - Plumbing Fixtures



Note:

Campus Assessment Report - 1986 Baseball Pressbox

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:

Campus Assessment Report - 1986 Baseball Pressbox

System: D5010 - Electrical Service/Distribution




Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Campus Assessment Report - 1986 Baseball Pressbox

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$0	\$0	\$111,273	\$0	\$0	\$0	\$0	\$10,022	\$0	\$121,295
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$15,943	\$0	\$0	\$0	\$0	\$0	\$0	\$15,943
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$8,042	\$0	\$0	\$0	\$0	\$0	\$0	\$8,042
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$5,324	\$0	\$0	\$0	\$0	\$0	\$0	\$5,324
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,696	\$0	\$6,696
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$2,043	\$0	\$0	\$0	\$0	\$0	\$0	\$2,043
C1030 - Fittings	\$0	\$0	\$0	\$0	\$7,865	\$0	\$0	\$0	\$0	\$0	\$0	\$7,865
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$4,745	\$0	\$0	\$0	\$0	\$0	\$0	\$4,745
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$11,486	\$0	\$0	\$0	\$0	\$0	\$0	\$11,486


Campus Assessment Report - 1986 Baseball Pressbox

C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$8,840	\$0	\$0	\$0	\$0	\$0	\$0	\$8,840
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$9,267	\$0	\$0	\$0	\$0	\$0	\$0	\$9,267
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$780	\$0	\$0	\$0	\$0	\$0	\$0	\$780
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$5,516	\$0	\$0	\$0	\$0	\$0	\$0	\$5,516
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$4,968	\$0	\$0	\$0	\$0	\$0	\$0	\$4,968
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,326	\$0	\$3,326
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$8,580	\$0	\$0	\$0	\$0	\$0	\$0	\$8,580
D5020 - Lighting	\$0	\$0	\$0	\$0	\$7,967	\$0	\$0	\$0	\$0	\$0	\$0	\$7,967
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$9,908	\$0	\$0	\$0	\$0	\$0	\$0	\$9,908

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	1,100
Year Built:	1986
Last Renovation:	
Replacement Value:	\$168,245
Repair Cost:	\$45,473.19
Total FCI:	27.03 %
Total RSLI:	30.97 %
FCA Score:	72.97







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	1,100
Year Built:	1986	Last Renovation:	
Repair Cost:	\$45,473	Replacement Value:	\$168,245
FCI:	27.03 %	RSLI%:	30.97 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	69.00 %	0.00 %	\$0.00
B10 - Superstructure	69.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	51.47 %	5.74 %	\$1,634.00
B30 - Roofing	20.00 %	0.00 %	\$0.00
C10 - Interior Construction	38.33 %	0.00 %	\$0.00
C30 - Interior Finishes	23.74 %	52.50 %	\$17,170.19
D20 - Plumbing	13.33 %	0.00 %	\$0.00
D30 - HVAC	3.20 %	83.62 %	\$20,522.00
D50 - Electrical	15.11 %	0.00 %	\$0.00
E20 - Furnishings	0.00 %	110.00 %	\$6,147.00
Totals:	30.97 %	27.03 %	\$45,473.19

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Dec 06, 2016



2). South Elevation - Dec 06, 2016



3). West Elevation - Dec 06, 2016



4). North Elevation - Dec 06, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.93	S.F.	1,100	100	1986	2086		69.00 %	0.00 %	69			\$7,623
A1030	Slab on Grade	\$7.37	S.F.	1,100	100	1986	2086		69.00 %	0.00 %	69			\$8,107
B1020	Roof Construction	\$5.98	S.F.	1,100	100	1986	2086		69.00 %	0.00 %	69			\$6,578
B2010	Exterior Walls	\$18.04	S.F.	1,100	100	1986	2086		69.00 %	0.00 %	69			\$19,844
B2020	Exterior Windows	\$6.47	S.F.	1,100	30	1986	2016	2021	13.33 %	0.00 %	4			\$7,117
B2030	Exterior Doors	\$1.35	S.F.	1,100	30	1986	2016		0.00 %	110.03 %	-1		\$1,634.00	\$1,485
B3010140	Asphalt Shingles	\$4.32	S.F.	1,100	20	1986	2006	2021	20.00 %	0.00 %	4			\$4,752
C1010	Partitions	\$10.34	S.F.	1,100	75	1986	2061		58.67 %	0.00 %	44			\$11,374
C1020	Interior Doors	\$2.20	S.F.	1,100	30	1986	2016	2021	13.33 %	0.00 %	4			\$2,420
C1030	Fittings	\$8.47	S.F.	1,100	20	1986	2006	2021	20.00 %	0.00 %	4			\$9,317
C3010	Wall Finishes	\$7.46	S.F.	1,100	10	1986	1996	2021	40.00 %	0.00 %	4			\$8,206
C3020	Floor Finishes	\$12.74	S.F.	1,100	20	1986	2006	2021	20.00 %	122.52 %	4		\$17,170.19	\$14,014
C3030	Ceiling Finishes	\$9.53	S.F.	1,100	25	1986	2011	2021	16.00 %	0.00 %	4			\$10,483
D2010	Plumbing Fixtures	\$9.98	S.F.	1,100	30	1986	2016	2021	13.33 %	0.00 %	4			\$10,978
D2020	Domestic Water Distribution	\$0.84	S.F.	1,100	30	1986	2016	2021	13.33 %	0.00 %	4			\$924
D2030	Sanitary Waste	\$5.94	S.F.	1,100	30	1986	2016	2021	13.33 %	0.00 %	4			\$6,534
D3040	Distribution Systems	\$5.35	S.F.	1,100	30	1986	2016	2021	13.33 %	0.00 %	4			\$5,885
D3050	Terminal & Package Units	\$16.96	S.F.	1,100	15	1986	2001		0.00 %	110.00 %	-16		\$20,522.00	\$18,656
D5010	Electrical Service/Distribution	\$1.47	S.F.	1,100	40	1986	2026		22.50 %	0.00 %	9			\$1,617
D5020	Branch Wiring	\$2.55	S.F.	1,100	30	1986	2016	2021	13.33 %	0.00 %	4			\$2,805
D5020	Lighting	\$3.58	S.F.	1,100	30	1986	2016	2021	13.33 %	0.00 %	4			\$3,938
E2010	Fixed Furnishings	\$5.08	S.F.	1,100	20	1986	2006		0.00 %	110.00 %	-11		\$6,147.00	\$5,588
Total									30.97 %	27.03 %			\$45,473.19	\$168,245

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:


Campus Assessment Report - 1986 Concession

System: B3010140 - Asphalt Shingles





Note:

System: C1010 - Partitions



Note:



System: C1020 - Interior Doors



Note:



Campus Assessment Report - 1986 Concession

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:

System: C3020 - Floor Finishes



Note:




Campus Assessment Report - 1986 Concession

System: C3030 - Ceiling Finishes




Note:

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:


Campus Assessment Report - 1986 Concession

System: D2030 - Sanitary Waste





Note:

System: D3040 - Distribution Systems



Note:


System: D3050 - Terminal & Package Units



Note:


Campus Assessment Report - 1986 Concession

System: D5010 - Electrical Service/Distribution




Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Campus Assessment Report - 1986 Concession

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$45,473	\$0	\$0	\$0	\$110,100	\$0	\$0	\$0	\$0	\$2,321	\$0	\$157,894
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$8,812	\$0	\$0	\$0	\$0	\$0	\$0	\$8,812
B2030 - Exterior Doors	\$1,634	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,634
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$7,809	\$0	\$0	\$0	\$0	\$0	\$0	\$7,809
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$2,996	\$0	\$0	\$0	\$0	\$0	\$0	\$2,996
C1030 - Fittings	\$0	\$0	\$0	\$0	\$11,535	\$0	\$0	\$0	\$0	\$0	\$0	\$11,535
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$10,160	\$0	\$0	\$0	\$0	\$0	\$0	\$10,160
C3020 - Floor Finishes	\$17,170	\$0	\$0	\$0	\$17,350	\$0	\$0	\$0	\$0	\$0	\$0	\$34,520
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$12,978	\$0	\$0	\$0	\$0	\$0	\$0	\$12,978
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1986 Concession

D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$13,592	\$0	\$0	\$0	\$0	\$0	\$0	\$13,592
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$1,144	\$0	\$0	\$0	\$0	\$0	\$0	\$1,144
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$8,089	\$0	\$0	\$0	\$0	\$0	\$0	\$8,089
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$7,287	\$0	\$0	\$0	\$0	\$0	\$0	\$7,287
D3050 - Terminal & Package Units	\$20,522	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$20,522
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,321	\$0	\$2,321
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$3,473	\$0	\$0	\$0	\$0	\$0	\$0	\$3,473
D5020 - Lighting	\$0	\$0	\$0	\$0	\$4,876	\$0	\$0	\$0	\$0	\$0	\$0	\$4,876
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$6,147	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,147

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$45,473.19

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$45,473.19


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2030	Exterior Doors	\$0.00	\$0.00	\$1,634.00	\$0.00	\$0.00	\$1,634.00
C3020	Floor Finishes	\$0.00	\$0.00	\$17,170.19	\$0.00	\$0.00	\$17,170.19
D3050	Terminal & Package Units	\$0.00	\$0.00	\$20,522.00	\$0.00	\$0.00	\$20,522.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$6,147.00	\$0.00	\$0.00	\$6,147.00
	Total:	\$0.00	\$0.00	\$45,473.19	\$0.00	\$0.00	\$45,473.19

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$45,473.19

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2030 - Exterior Doors



Location: Exterior of the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 1,100.00
Unit of Measure: S.F.
Estimate: \$1,634.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The exterior doors are beyond their service life and should be replaced.

System: C3020 - Floor Finishes



Location: Concession Room
Distress: Failing
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace epoxy flooring
Qty: 8.14
Unit of Measure: C.S.F.
Estimate: \$17,170.19
Assessor Name: Eduardo Lopez
Date Created: 12/06/2016

Notes: The epoxy flooring is in poor condition and should be replaced.

System: D3050 - Terminal & Package Units



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 1,100.00
Unit of Measure: S.F.
Estimate: \$20,522.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The unit heaters are beyond their service life and should be replaced.

System: E2010 - Fixed Furnishings



Location: Concession Room
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 1,100.00
Unit of Measure: S.F.
Estimate: \$6,147.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The fixed furnishings are beyond their service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	3,200
Year Built:	1986
Last Renovation:	
Replacement Value:	\$759,680
Repair Cost:	\$155,092.00
Total FCI:	20.42 %
Total RSLI:	33.69 %
FCA Score:	79.58







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	3,200
Year Built:	1986	Last Renovation:	
Repair Cost:	\$155,092	Replacement Value:	\$759,680
FCI:	20.42 %	RSLI%:	33.69 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	69.00 %	0.00 %	\$0.00
B10 - Superstructure	69.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	50.25 %	0.00 %	\$0.00
B30 - Roofing	20.00 %	0.00 %	\$0.00
C10 - Interior Construction	20.05 %	0.00 %	\$0.00
C30 - Interior Finishes	11.29 %	51.25 %	\$73,286.00
D20 - Plumbing	8.07 %	65.50 %	\$35,130.00
D30 - HVAC	23.00 %	0.00 %	\$0.00
D50 - Electrical	14.25 %	0.00 %	\$0.00
E10 - Equipment	0.00 %	110.00 %	\$28,794.00
E20 - Furnishings	0.00 %	110.00 %	\$17,882.00
Totals:	33.69 %	20.42 %	\$155,092.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). West Elevation - Dec 06, 2016



2). South Elevation - Dec 06, 2016



3). East Elevation - Dec 06, 2016



4). North Elevation - Dec 06, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	3,200	100	1986	2086		69.00 %	0.00 %	69			\$64,416
A1030	Slab on Grade	\$19.75	S.F.	3,200	100	1986	2086		69.00 %	0.00 %	69			\$63,200
B1020	Roof Construction	\$16.26	S.F.	3,200	100	1986	2086		69.00 %	0.00 %	69			\$52,032
B2010	Exterior Walls	\$29.79	S.F.	3,200	100	1986	2086		69.00 %	0.00 %	69			\$95,328
B2020	Exterior Windows	\$6.47	S.F.	3,200	30	1986	2016	2021	13.33 %	0.00 %	4			\$20,704
B2030	Exterior Doors	\$8.66	S.F.	3,200	30	1986	2016	2021	13.33 %	0.00 %	4			\$27,712
B3010140	Asphalt Shingles	\$4.32	S.F.	3,200	20	1986	2006	2021	20.00 %	0.00 %	4			\$13,824
C1010	Partitions	\$6.22	S.F.	3,200	40	1986	2026		22.50 %	0.00 %	9			\$19,904
C1020	Interior Doors	\$2.20	S.F.	3,200	30	1986	2016	2021	13.33 %	0.00 %	4			\$7,040
C1030	Fittings	\$8.47	S.F.	3,200	20	1986	2006	2021	20.00 %	0.00 %	4			\$27,104
C3010	Wall Finishes	\$5.11	S.F.	3,200	10	1986	1996	2021	40.00 %	0.00 %	4			\$16,352
C3020	Floor Finishes	\$20.82	S.F.	3,200	20	1986	2006		0.00 %	110.00 %	-11		\$73,286.00	\$66,624
C3030	Ceiling Finishes	\$18.76	S.F.	3,200	25	1986	2011	2021	16.00 %	0.00 %	4			\$60,032
D2010	Plumbing Fixtures	\$9.98	S.F.	3,200	30	1986	2016		0.00 %	110.00 %	-1		\$35,130.00	\$31,936
D2020	Domestic Water Distribution	\$0.84	S.F.	3,200	30	2007	2037		66.67 %	0.00 %	20			\$2,688
D2030	Sanitary Waste	\$5.94	S.F.	3,200	30	1986	2016	2021	13.33 %	0.00 %	4			\$19,008
D3040	Distribution Systems	\$5.35	S.F.	3,200	30	1986	2016	2021	13.33 %	0.00 %	4			\$17,120
D3050	Terminal & Package Units	\$16.96	S.F.	3,200	15	1986	2001	2021	26.67 %	0.00 %	4			\$54,272
D3060	Controls & Instrumentation	\$3.48	S.F.	3,200	20	1986	2006	2021	20.00 %	0.00 %	4			\$11,136
D5010	Electrical Service/Distribution	\$1.47	S.F.	3,200	40	1986	2026		22.50 %	0.00 %	9			\$4,704
D5020	Branch Wiring	\$3.58	S.F.	3,200	30	1986	2016	2021	13.33 %	0.00 %	4			\$11,456
D5020	Lighting	\$9.58	S.F.	3,200	30	1986	2016	2021	13.33 %	0.00 %	4			\$30,656
E1010	Commercial Equipment	\$8.18	S.F.	3,200	20	1986	2006		0.00 %	110.00 %	-11		\$28,794.00	\$26,176
E2010	Fixed Furnishings	\$5.08	S.F.	3,200	20	1986	2006		0.00 %	110.00 %	-11		\$17,882.00	\$16,256
Total									33.69 %	20.42 %			\$155,092.00	\$759,680

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls





Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:


Campus Assessment Report - 1986 Football Fieldhouse

System: B3010140 - Asphalt Shingles



Note:

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note:


Campus Assessment Report - 1986 Football Fieldhouse

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:

System: C3020 - Floor Finishes



Note: The epoxy and carpet are in poor condition and should be replaced.

Campus Assessment Report - 1986 Football Fieldhouse

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:


Campus Assessment Report - 1986 Football Fieldhouse

System: D2030 - Sanitary Waste




Note:

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:

Campus Assessment Report - 1986 Football Fieldhouse

System: D3060 - Controls & Instrumentation




Note:

System: D5010 - Electrical Service/Distribution



Note:


System: D5020 - Branch Wiring



Note:

Campus Assessment Report - 1986 Football Fieldhouse

System: D5020 - Lighting



Note:

System: E1010 - Commercial Equipment



Note: The commercial equipment is beyond its service life and should be replaced.

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$155,092	\$0	\$0	\$0	\$397,343	\$0	\$0	\$0	\$0	\$35,318	\$0	\$587,752
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$25,632	\$0	\$0	\$0	\$0	\$0	\$0	\$25,632
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$34,309	\$0	\$0	\$0	\$0	\$0	\$0	\$34,309
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$22,716	\$0	\$0	\$0	\$0	\$0	\$0	\$22,716
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$28,567	\$0	\$28,567
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$8,716	\$0	\$0	\$0	\$0	\$0	\$0	\$8,716
C1030 - Fittings	\$0	\$0	\$0	\$0	\$33,556	\$0	\$0	\$0	\$0	\$0	\$0	\$33,556
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$20,245	\$0	\$0	\$0	\$0	\$0	\$0	\$20,245
C3020 - Floor Finishes	\$73,286	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$73,286
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$74,323	\$0	\$0	\$0	\$0	\$0	\$0	\$74,323
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1986 Football Fieldhouse

D2010 - Plumbing Fixtures	\$35,130	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$35,130
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$23,533	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$23,533
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$21,196	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$21,196
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$67,192	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$67,192
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$13,787	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,787
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,751	\$0	\$6,751
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$14,184	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,184
D5020 - Lighting	\$0	\$0	\$0	\$0	\$37,954	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$37,954
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$28,794	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$28,794
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$17,882	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$17,882

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$155,092.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$155,092.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
C3020	Floor Finishes	\$0.00	\$0.00	\$73,286.00	\$0.00	\$0.00	\$73,286.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$35,130.00	\$0.00	\$0.00	\$35,130.00
E1010	Commercial Equipment	\$0.00	\$0.00	\$28,794.00	\$0.00	\$0.00	\$28,794.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$17,882.00	\$0.00	\$0.00	\$17,882.00
	Total:	\$0.00	\$0.00	\$155,092.00	\$0.00	\$0.00	\$155,092.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: C3020 - Floor Finishes



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 3,200.00
Unit of Measure: S.F.
Estimate: \$73,286.00
Assessor Name: Somnath Das
Date Created: 11/30/2016

Notes: The epoxy and carpet are in poor condition and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 3,200.00
Unit of Measure: S.F.
Estimate: \$35,130.00
Assessor Name: Somnath Das
Date Created: 12/06/2016

Notes: The plumbing fixtures are beyond their service life and should be replaced.

System: E1010 - Commercial Equipment



Location: Laundry Room
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 3,200.00
Unit of Measure: S.F.
Estimate: \$28,794.00
Assessor Name: Somnath Das
Date Created: 12/06/2016

Notes: The commercial equipment is beyond its service life and should be replaced.

System: E2010 - Fixed Furnishings



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 3,200.00
Unit of Measure: S.F.
Estimate: \$17,882.00
Assessor Name: Somnath Das
Date Created: 12/06/2016

Notes: The fixed furnishings are beyond their service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	250
Year Built:	1986
Last Renovation:	
Replacement Value:	\$51,404
Repair Cost:	\$4,295.00
Total FCI:	8.36 %
Total RSLI:	40.50 %
FCA Score:	91.64







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	250
Year Built:	1986	Last Renovation:	
Repair Cost:	\$4,295	Replacement Value:	\$51,404
FCI:	8.36 %	RSLI%:	40.50 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	69.00 %	0.00 %	\$0.00
B10 - Superstructure	69.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	43.15 %	0.00 %	\$0.00
B30 - Roofing	10.53 %	52.04 %	\$1,724.00
C10 - Interior Construction	13.33 %	0.00 %	\$0.00
C20 - Stairs	69.00 %	0.00 %	\$0.00
C30 - Interior Finishes	24.38 %	0.00 %	\$0.00
D20 - Plumbing	13.33 %	0.00 %	\$0.00
D50 - Electrical	15.99 %	0.00 %	\$0.00
E20 - Furnishings	0.00 %	109.97 %	\$2,571.00
Totals:	40.50 %	8.36 %	\$4,295.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Dec 06, 2016



2). East Elevation - Dec 06, 2016



3). North Elevation - Dec 06, 2016



4). West Elevation - Dec 06, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	250	100	1986	2086		69.00 %	0.00 %	69			\$5,033
A1030	Slab on Grade	\$19.75	S.F.	250	100	1986	2086		69.00 %	0.00 %	69			\$4,938
B1010	Floor Construction	\$11.44	S.F.	250	100	1986	2086		69.00 %	0.00 %	69			\$2,860
B1020	Roof Construction	\$16.26	S.F.	250	100	1986	2086		69.00 %	0.00 %	69			\$4,065
B2010	Exterior Walls	\$29.79	S.F.	250	100	1986	2086		69.00 %	0.00 %	69			\$7,448
B2020	Exterior Windows	\$17.17	S.F.	250	30	1986	2016	2021	13.33 %	0.00 %	4			\$4,293
B2030	Exterior Doors	\$8.66	S.F.	250	30	1986	2016	2021	13.33 %	0.00 %	4			\$2,165
B3010120	Single Ply Membrane	\$6.98	S.F.	250	20	1986	2006	2021	20.00 %	0.00 %	4			\$1,745
B3020	Roof Openings	\$6.27	S.F.	250	25	1986	2011		0.00 %	109.95 %	-6		\$1,724.00	\$1,568
C1020	Interior Doors	\$2.20	S.F.	250	30	1986	2016	2021	13.33 %	0.00 %	4			\$550
C2010	Stair Construction	\$1.77	S.F.	250	100	1986	2086		69.00 %	0.00 %	69			\$443
C3010	Wall Finishes	\$5.11	S.F.	250	10	1986	1996	2021	40.00 %	0.00 %	4			\$1,278
C3030	Ceiling Finishes	\$9.52	S.F.	250	25	1986	2011	2021	16.00 %	0.00 %	4			\$2,380
D2010	Plumbing Fixtures	\$9.98	S.F.	250	30	1986	2016	2021	13.33 %	0.00 %	4			\$2,495
D2020	Domestic Water Distribution	\$6.14	S.F.	250	30	1986	2016	2021	13.33 %	0.00 %	4			\$1,535
D5010	Electrical Service/Distribution	\$7.26	S.F.	250	40	1986	2026		22.50 %	0.00 %	9			\$1,815
D5020	Branch Wiring	\$9.24	S.F.	250	30	1986	2016	2021	13.33 %	0.00 %	4			\$2,310
D5020	Lighting	\$8.58	S.F.	250	30	1986	2016	2021	13.33 %	0.00 %	4			\$2,145
E2010	Fixed Furnishings	\$9.35	S.F.	250	20	1986	2006		0.00 %	109.97 %	-11		\$2,571.00	\$2,338
Total									40.50 %	8.36 %			\$4,295.00	\$51,404

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1986 Pressbox

System: B3010120 - Single Ply Membrane



Note:

System: B3020 - Roof Openings



Note:


System: C1020 - Interior Doors



Note:


Campus Assessment Report - 1986 Pressbox

System: C2010 - Stair Construction




Note:

System: C3010 - Wall Finishes



Note:


System: C3030 - Ceiling Finishes



Note:

Campus Assessment Report - 1986 Pressbox

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

System: D5010 - Electrical Service/Distribution



Note:

Campus Assessment Report - 1986 Pressbox

System: D5020 - Branch Wiring




Note:

System: D5020 - Lighting



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$4,295	\$0	\$0	\$0	\$26,658	\$0	\$0	\$0	\$0	\$2,606	\$0	\$33,558
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$5,315	\$0	\$0	\$0	\$0	\$0	\$0	\$5,315
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$2,681	\$0	\$0	\$0	\$0	\$0	\$0	\$2,681
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$2,947	\$0	\$0	\$0	\$0	\$0	\$0	\$2,947
B3020 - Roof Openings	\$1,724	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,724
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$681	\$0	\$0	\$0	\$0	\$0	\$0	\$681
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$1,581	\$0	\$0	\$0	\$0	\$0	\$0	\$1,581
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$2,947	\$0	\$0	\$0	\$0	\$0	\$0	\$2,947
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1986 Pressbox

D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$3,090	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,090
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$1,901	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,901
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,606	\$0	\$2,606
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$2,860	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,860
D5020 - Lighting	\$0	\$0	\$0	\$0	\$2,656	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,656
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$2,571	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,571

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$4,295.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B3020	Roof Openings	\$0.00	\$0.00	\$1,724.00	\$0.00	\$0.00	\$1,724.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$2,571.00	\$0.00	\$0.00	\$2,571.00
	Total:	\$0.00	\$0.00	\$4,295.00	\$0.00	\$0.00	\$4,295.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$4,295.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B3020 - Roof Openings



Location: Roof
Distress: Beyond Service Life
Category: Safety / Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 250.00
Unit of Measure: S.F.
Estimate: \$1,724.00
Assessor Name: Eduardo Lopez
Date Created: 12/06/2016

Notes: The roof hatch is beyond its service life and should be replaced with a OSHA complaint roof hatch.

System: E2010 - Fixed Furnishings



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 250.00
Unit of Measure: S.F.
Estimate: \$2,571.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The fixed furnishing is beyond its service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	550
Year Built:	1986
Last Renovation:	
Replacement Value:	\$76,878
Repair Cost:	\$6,310.00
Total FCI:	8.21 %
Total RSLI:	35.34 %
FCA Score:	91.79







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	550
Year Built:	1986	Last Renovation:	
Repair Cost:	\$6,310	Replacement Value:	\$76,878
FCI:	8.21 %	RSLI%:	35.34 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	69.00 %	0.00 %	\$0.00
B10 - Superstructure	69.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	52.84 %	0.00 %	\$0.00
B30 - Roofing	20.00 %	0.00 %	\$0.00
C10 - Interior Construction	38.33 %	0.00 %	\$0.00
C30 - Interior Finishes	26.54 %	0.00 %	\$0.00
D20 - Plumbing	17.18 %	0.00 %	\$0.00
D30 - HVAC	20.27 %	26.38 %	\$3,237.00
D50 - Electrical	15.11 %	0.00 %	\$0.00
E20 - Furnishings	0.00 %	109.99 %	\$3,073.00
Totals:	35.34 %	8.21 %	\$6,310.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Dec 06, 2016



2). East Elevation - Dec 06, 2016



3). South Elevation - Dec 06, 2016



4). West Elevation - Dec 06, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.93	S.F.	550	100	1986	2086		69.00 %	0.00 %	69			\$3,812
A1030	Slab on Grade	\$7.37	S.F.	550	100	1986	2086		69.00 %	0.00 %	69			\$4,054
B1020	Roof Construction	\$5.98	S.F.	550	100	1986	2086		69.00 %	0.00 %	69			\$3,289
B2010	Exterior Walls	\$18.04	S.F.	550	100	1986	2086		69.00 %	0.00 %	69			\$9,922
B2020	Exterior Windows	\$6.47	S.F.	550	30	1986	2016	2021	13.33 %	0.00 %	4			\$3,559
B2030	Exterior Doors	\$0.91	S.F.	550	30	1986	2016	2021	13.33 %	0.00 %	4			\$501
B3010140	Asphalt Shingles	\$4.32	S.F.	550	20	1986	2006	2021	20.00 %	0.00 %	4			\$2,376
C1010	Partitions	\$10.34	S.F.	550	75	1986	2061		58.67 %	0.00 %	44			\$5,687
C1020	Interior Doors	\$2.20	S.F.	550	30	1986	2016	2021	13.33 %	0.00 %	4			\$1,210
C1030	Fittings	\$8.47	S.F.	550	20	1986	2006	2021	20.00 %	0.00 %	4			\$4,659
C3010	Wall Finishes	\$7.46	S.F.	550	10	1986	1996	2021	40.00 %	0.00 %	4			\$4,103
C3030	Ceiling Finishes	\$9.53	S.F.	550	25	1986	2011	2021	16.00 %	0.00 %	4			\$5,242
D2010	Plumbing Fixtures	\$9.98	S.F.	550	30	1986	2016	2021	13.33 %	0.00 %	4			\$5,489
D2020	Domestic Water Distribution	\$0.84	S.F.	550	30	2014	2044		90.00 %	0.00 %	27			\$462
D2030	Sanitary Waste	\$5.94	S.F.	550	30	1986	2016	2021	13.33 %	0.00 %	4			\$3,267
D3040	Distribution Systems	\$5.35	S.F.	550	30	1986	2016		0.00 %	109.99 %	-1		\$3,237.00	\$2,943
D3050	Terminal & Package Units	\$16.96	S.F.	550	15	1986	2001	2021	26.67 %	0.00 %	4			\$9,328
D5010	Electrical Service/Distribution	\$1.47	S.F.	550	40	1986	2026		22.50 %	0.00 %	9			\$809
D5020	Branch Wiring	\$2.55	S.F.	550	30	1986	2016	2021	13.33 %	0.00 %	4			\$1,403
D5020	Lighting	\$3.58	S.F.	550	30	1986	2016	2021	13.33 %	0.00 %	4			\$1,969
E2010	Fixed Furnishings	\$5.08	S.F.	550	20	1986	2006		0.00 %	109.99 %	-11		\$3,073.00	\$2,794
Total									35.34 %	8.21 %			\$6,310.00	\$76,878

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:


Campus Assessment Report - 1986 Softball Concession

System: B3010140 - Asphalt Shingles




Note:

System: C1010 - Partitions



Note:


System: C1020 - Interior Doors



Note:



Campus Assessment Report - 1986 Softball Concession

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

Campus Assessment Report - 1986 Softball Concession

System: D2010 - Plumbing Fixtures




Note:

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

Campus Assessment Report - 1986 Softball Concession

System: D3040 - Distribution Systems




Note:

System: D3050 - Terminal & Package Units



Note:


System: D5010 - Electrical Service/Distribution



Note:

Campus Assessment Report - 1986 Softball Concession

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$6,310	\$0	\$0	\$0	\$54,328	\$0	\$0	\$0	\$0	\$1,160	\$0	\$61,798
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$4,405	\$0	\$0	\$0	\$0	\$0	\$0	\$4,405
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$620	\$0	\$0	\$0	\$0	\$0	\$0	\$620
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$3,904	\$0	\$0	\$0	\$0	\$0	\$0	\$3,904
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$1,498	\$0	\$0	\$0	\$0	\$0	\$0	\$1,498
C1030 - Fittings	\$0	\$0	\$0	\$0	\$5,767	\$0	\$0	\$0	\$0	\$0	\$0	\$5,767
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$5,079	\$0	\$0	\$0	\$0	\$0	\$0	\$5,079
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$6,490	\$0	\$0	\$0	\$0	\$0	\$0	\$6,490
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$6,796	\$0	\$0	\$0	\$0	\$0	\$0	\$6,796


Campus Assessment Report - 1986 Softball Concession

D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$4,045	\$0	\$0	\$0	\$0	\$0	\$0	\$4,045
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$3,237	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,237
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$11,549	\$0	\$0	\$0	\$0	\$0	\$0	\$11,549
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,160	\$0	\$1,160
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$1,737	\$0	\$0	\$0	\$0	\$0	\$0	\$1,737
D5020 - Lighting	\$0	\$0	\$0	\$0	\$2,438	\$0	\$0	\$0	\$0	\$0	\$0	\$2,438
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$3,073	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,073

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$6,310.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
D3040	Distribution Systems	\$0.00	\$0.00	\$3,237.00	\$0.00	\$0.00	\$3,237.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$3,073.00	\$0.00	\$0.00	\$3,073.00
	Total:	\$0.00	\$0.00	\$6,310.00	\$0.00	\$0.00	\$6,310.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: D3040 - Distribution Systems



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 550.00
Unit of Measure: S.F.
Estimate: \$3,237.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The distribution systems are beyond their service life and should be replaced.

System: E2010 - Fixed Furnishings



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 550.00
Unit of Measure: S.F.
Estimate: \$3,073.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The fixed furnishing is beyond its service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	900
Year Built:	1986
Last Renovation:	
Replacement Value:	\$88,749
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	62.13 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary


Function:	HS -High School	Gross Area:	900
Year Built:	1986	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$88,749
FCI:	0.00 %	RSLI%:	62.13 %

No data found for this asset

No data found for this asset

No data found for this asset

10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	69.00 %	0.00 %	\$0.00
B10 - Superstructure	69.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	65.12 %	0.00 %	\$0.00
B30 - Roofing	20.00 %	0.00 %	\$0.00
D50 - Electrical	13.33 %	0.00 %	\$0.00
Totals:	62.13 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Dec 07, 2016



2). West Elevation - Dec 07, 2016



3). Northwest Elevation - Dec 07, 2016



4). East Elevation - Dec 07, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	900	100	1986	2086		69.00 %	0.00 %	69			\$18,117
A1030	Slab on Grade	\$19.75	S.F.	900	100	1986	2086		69.00 %	0.00 %	69			\$17,775
B1020	Roof Construction	\$16.26	S.F.	900	100	1986	2086		69.00 %	0.00 %	69			\$14,634
B2010	Exterior Walls	\$29.79	S.F.	900	100	1986	2086		69.00 %	0.00 %	69			\$26,811
B2030	Exterior Doors	\$2.23	S.F.	900	30	1986	2016	2021	13.33 %	0.00 %	4			\$2,007
B3010140	Asphalt Shingles	\$4.32	S.F.	900	20	1986	2006	2021	20.00 %	0.00 %	4			\$3,888
D5020	Branch Wiring	\$2.55	S.F.	900	30	1986	2016	2021	13.33 %	0.00 %	4			\$2,295
D5020	Lighting	\$3.58	S.F.	900	30	1986	2016	2021	13.33 %	0.00 %	4			\$3,222
Total									62.13 %					\$88,749

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1986 Tractor Building

System: B3010140 - Asphalt Shingles



Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$0	\$0	\$15,704	\$0	\$0	\$0	\$0	\$0	\$0	\$15,704
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$2,485	\$0	\$0	\$0	\$0	\$0	\$0	\$2,485
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$6,388	\$0	\$0	\$0	\$0	\$0	\$0	\$6,388
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$2,842	\$0	\$0	\$0	\$0	\$0	\$0	\$2,842
D5020 - Lighting	\$0	\$0	\$0	\$0	\$3,989	\$0	\$0	\$0	\$0	\$0	\$0	\$3,989

** Indicates non-renewable system*

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	1,632
Year Built:	2002
Last Renovation:	
Replacement Value:	\$225,363
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	69.76 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary


Function:	HS -High School	Gross Area:	1,632
Year Built:	2002	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$225,363
FCI:	0.00 %	RSLI%:	69.76 %

No data found for this asset

No data found for this asset

No data found for this asset

10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	85.00 %	0.00 %	\$0.00
B10 - Superstructure	85.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	77.12 %	0.00 %	\$0.00
B30 - Roofing	50.00 %	0.00 %	\$0.00
C10 - Interior Construction	50.00 %	0.00 %	\$0.00
C30 - Interior Finishes	38.10 %	0.00 %	\$0.00
D50 - Electrical	50.70 %	0.00 %	\$0.00
E10 - Equipment	25.00 %	0.00 %	\$0.00
E20 - Furnishings	25.00 %	0.00 %	\$0.00
Totals:	69.76 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). Southwest Elevation - Dec 07, 2016



2). Southeast Elevation - Dec 07, 2016



3). Northeast Elevation - Dec 07, 2016



4). Northwest Elevation - Dec 07, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing


The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	1,632	100	2002	2102		85.00 %	0.00 %	85			\$32,852
A1030	Slab on Grade	\$19.75	S.F.	1,632	100	2002	2102		85.00 %	0.00 %	85			\$32,232
B1020	Roof Construction	\$16.26	S.F.	1,632	100	2002	2102		85.00 %	0.00 %	85			\$26,536
B2010	Exterior Walls	\$29.79	S.F.	1,632	100	2002	2102		85.00 %	0.00 %	85			\$48,617
B2030	Exterior Doors	\$8.66	S.F.	1,632	30	2002	2032		50.00 %	0.00 %	15			\$14,133
B3010130	Preformed Metal Roofing	\$9.66	S.F.	1,632	30	2002	2032		50.00 %	0.00 %	15			\$15,765
C1020	Interior Doors	\$0.36	S.F.	1,632	30	2002	2032		50.00 %	0.00 %	15			\$588
C3010	Wall Finishes	\$3.79	S.F.	1,632	10	2002	2012	2021	40.00 %	0.00 %	4			\$6,185
C3020	Floor Finishes	\$1.93	S.F.	1,632	20	2002	2022		25.00 %	0.00 %	5			\$3,150
C3030	Ceiling Finishes	\$9.53	S.F.	1,632	25	2002	2027		40.00 %	0.00 %	10			\$15,553
D5010	Electrical Service/Distribution	\$0.78	S.F.	1,632	40	2002	2042		62.50 %	0.00 %	25			\$1,273
D5020	Branch Wiring	\$3.58	S.F.	1,632	30	2002	2032		50.00 %	0.00 %	15			\$5,843
D5020	Lighting	\$9.58	S.F.	1,632	30	2002	2032		50.00 %	0.00 %	15			\$15,635
E1020	Institutional Equipment	\$1.98	S.F.	1,632	20	2002	2022		25.00 %	0.00 %	5			\$3,231
E2010	Fixed Furnishings	\$2.31	S.F.	1,632	20	2002	2022		25.00 %	0.00 %	5			\$3,770
Total									69.76 %					\$225,363

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2030 - Exterior Doors



Note:


System: B3010130 - Preformed Metal Roofing



Note:


Campus Assessment Report - 2002 Metal Building

System: C1020 - Interior Doors




Note:

System: C3010 - Wall Finishes



Note:




System: C3020 - Floor Finishes



Note:

Campus Assessment Report - 2002 Metal Building

System: C3030 - Ceiling Finishes




Note:

System: D5010 - Electrical Service/Distribution



Note:

System: D5020 - Branch Wiring



Note:

Campus Assessment Report - 2002 Metal Building

System: D5020 - Lighting



Note:

System: E1020 - Institutional Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%


Campus Assessment Report - 2002 Metal Building

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$0	\$0	\$7,658	\$12,944	\$0	\$0	\$0	\$0	\$22,992	\$43,594
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$7,658	\$0	\$0	\$0	\$0	\$0	\$0	\$7,658
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$4,017	\$0	\$0	\$0	\$0	\$0	\$4,017
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$22,992	\$22,992
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$4,120	\$0	\$0	\$0	\$0	\$0	\$4,120
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$4,808	\$0	\$0	\$0	\$0	\$0	\$4,808

** Indicates non-renewable system*

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	254,932
Year Built:	1985
Last Renovation:	
Replacement Value:	\$10,130,996
Repair Cost:	\$1,332,020.00
Total FCI:	13.15 %
Total RSLI:	31.72 %
FCA Score:	86.85







Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	254,932
Year Built:	1985	Last Renovation:	
Repair Cost:	\$1,332,020	Replacement Value:	\$10,130,996
FCI:	13.15 %	RSLI%:	31.72 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	32.47 %	13.88 %	\$891,752.00
G30 - Site Mechanical Utilities	34.29 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	22.76 %	35.32 %	\$440,268.00
Totals:	31.72 %	13.15 %	\$1,332,020.00

Photo Album

The photo album consists of the various cardinal directions of the building..

- 1). Aerial Image of Triton High Sschool - Dec 07, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$3.76	S.F.	254,932	25	2014	2039		88.00 %	0.00 %	22			\$958,544
G2020	Parking Lots	\$1.61	S.F.	254,932	25	2014	2039		88.00 %	0.00 %	22			\$410,441
G2030	Pedestrian Paving	\$1.98	S.F.	254,932	30	1985	2015		0.00 %	110.00 %	-2		\$555,242.00	\$504,765
G2040105	Fence & Guardrails	\$1.20	S.F.	254,932	30	1985	2015		0.00 %	110.00 %	-2		\$336,510.00	\$305,918
G2040950	Baseball Field	\$5.78	S.F.	254,932	20	1985	2005	2021	20.00 %	0.00 %	4			\$1,473,507
G2040950	Football Field	\$3.38	S.F.	254,932	20	1985	2005	2021	20.00 %	0.00 %	4			\$861,670
G2040950	Softball Field	\$2.01	S.F.	254,932	20	1985	2005	2021	20.00 %	0.00 %	4			\$512,413
G2040950	Tennis Courts	\$1.80	S.F.	254,932	20	1985	2005	2021	20.00 %	0.00 %	4			\$458,878
G2040950	Track	\$1.78	S.F.	254,932	20	1985	2005	2021	20.00 %	0.00 %	4			\$453,779
G2050	Landscaping	\$1.91	S.F.	254,932	15	1985	2000	2021	26.67 %	0.00 %	4			\$486,920
G3010	Water Supply	\$2.42	S.F.	254,932	50	1985	2035		36.00 %	0.00 %	18			\$616,935
G3020	Sanitary Sewer	\$1.52	S.F.	254,932	50	1985	2035		36.00 %	0.00 %	18			\$387,497
G3030	Storm Sewer	\$4.67	S.F.	254,932	50	1985	2035		36.00 %	0.00 %	18			\$1,190,532
G3060	Fuel Distribution	\$1.03	S.F.	254,932	40	1985	2025		20.00 %	0.00 %	8			\$262,580
G4010	Electrical Distribution	\$2.44	S.F.	254,932	50	1985	2035		36.00 %	0.00 %	18			\$622,034
G4020	Site Lighting	\$1.57	S.F.	254,932	30	1985	2015		0.00 %	110.00 %	-2		\$440,268.00	\$400,243
G4030	Site Communications & Security	\$0.88	S.F.	254,932	15	1985	2000	2021	26.67 %	0.00 %	4			\$224,340
Total									31.72 %	13.15 %			\$1,332,020.00	\$10,130,996

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways




Note:

System: G2020 - Parking Lots



Note:

System: G2030 - Pedestrian Paving



Note:

Campus Assessment Report - Site

System: G2040105 - Fence & Guardrails



Note:

System: G2040950 - Baseball Field



Note:

System: G2040950 - Football Field



Note:

Campus Assessment Report - Site

System: G2040950 - Softball Field





Note:

System: G2040950 - Tennis Courts



Note:

System: G2040950 - Track



Note:

Campus Assessment Report - Site

System: G2050 - Landscaping



Note:

System: G3010 - Water Supply



Note:

System: G3020 - Sanitary Sewer



Note:

Campus Assessment Report - Site

System: G3030 - Storm Sewer



Note:

System: G3060 - Fuel Distribution



Note:

System: G4010 - Electrical Distribution



Note:


Campus Assessment Report - Site

System: G4020 - Site Lighting



Note:

System: G4030 - Site Communications & Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$1,332,020	\$0	\$0	\$0	\$4,933,157	\$0	\$0	\$0	\$365,891	\$0	\$0	\$6,631,068
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2020 - Parking Lots	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2030 - Pedestrian Paving	\$555,242	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$555,242
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040105 - Fence & Guardrails	\$336,510	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$336,510
G2040950 - Baseball Field	\$0	\$0	\$0	\$0	\$1,824,290	\$0	\$0	\$0	\$0	\$0	\$0	\$1,824,290
G2040950 - Football Field	\$0	\$0	\$0	\$0	\$1,066,799	\$0	\$0	\$0	\$0	\$0	\$0	\$1,066,799
G2040950 - Softball Field	\$0	\$0	\$0	\$0	\$634,399	\$0	\$0	\$0	\$0	\$0	\$0	\$634,399
G2040950 - Tennis Courts	\$0	\$0	\$0	\$0	\$568,117	\$0	\$0	\$0	\$0	\$0	\$0	\$568,117
G2040950 - Track	\$0	\$0	\$0	\$0	\$561,806	\$0	\$0	\$0	\$0	\$0	\$0	\$561,806
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3060 - Fuel Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$365,891	\$0	\$0	\$365,891
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$440,268	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$440,268
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$277,746	\$0	\$0	\$0	\$0	\$0	\$0	\$277,746

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$1,332,020.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$1,332,020.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
G2030	Pedestrian Paving	\$555,242.00	\$0.00	\$0.00	\$0.00	\$0.00	\$555,242.00
G2040105	Fence & Guardrails	\$0.00	\$0.00	\$336,510.00	\$0.00	\$0.00	\$336,510.00
G4020	Site Lighting	\$0.00	\$0.00	\$440,268.00	\$0.00	\$0.00	\$440,268.00
	Total:	\$555,242.00	\$0.00	\$776,778.00	\$0.00	\$0.00	\$1,332,020.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$1,332,020.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Currently Critical (Immediate):

System: G2030 - Pedestrian Paving



Location: Site
Distress: Beyond Service Life
Category: Safety
Priority: 1 - Currently Critical (Immediate)
Correction: Renew System
Qty: 254,932.00
Unit of Measure: S.F.
Estimate: \$555,242.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The pedestrian paving is beyond its service life and in some places they have become tripping hazards, the pedestrian paving needs to be repaved.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: G2040105 - Fence & Guardrails



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 254,932.00
Unit of Measure: S.F.
Estimate: \$336,510.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The fences and guardrails are either rusted or damaged and should be replaced.

System: G4020 - Site Lighting



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 254,932.00
Unit of Measure: S.F.
Estimate: \$440,268.00
Assessor Name: Eduardo Lopez
Date Created: 11/30/2016

Notes: The site lighting is beyond its service life and should be replaced with energy efficient LED lighting.
