

NC School District/430 Harnett County/Elementary School

Wayne Avenue Elementary

Final

Campus Assessment Report

March 11, 2017



Table of Contents

Campus Executive Summary	5
Campus Dashboard Summary	8
Campus Condition Summary	9
<u>1957 Main</u>	11
Executive Summary	11
Dashboard Summary	12
Condition Summary	13
Photo Album	14
Condition Detail	15
System Listing	16
System Notes	18
Renewal Schedule	27
Forecasted Sustainment Requirement	29
Deficiency Summary By System	30
Deficiency Summary By Priority	31
Deficiency By Priority Investment	32
Deficiency Summary By Category	33
Deficiency Details By Priority	34
<u>1998 Media Center</u>	42
Executive Summary	42
Dashboard Summary	43
Condition Summary	44
Photo Album	45
Condition Detail	46
System Listing	47
System Notes	48
Renewal Schedule	56
Forecasted Sustainment Requirement	58
Deficiency Summary By System	59

Campus Assessment Report

Deficiency Summary By Priority	60
Deficiency By Priority Investment	61
Deficiency Summary By Category	62
Deficiency Details By Priority	63
<u>2005 Multi Purpose Room</u>	64
Executive Summary	64
Dashboard Summary	65
Condition Summary	66
Photo Album	67
Condition Detail	68
System Listing	69
System Notes	70
Renewal Schedule	78
Forecasted Sustainment Requirement	80
Deficiency Summary By System	81
Deficiency Summary By Priority	82
Deficiency By Priority Investment	83
Deficiency Summary By Category	84
Deficiency Details By Priority	85
<u>Site</u>	86
Executive Summary	86
Dashboard Summary	87
Condition Summary	88
Photo Album	89
Condition Detail	90
System Listing	91
System Notes	92
Renewal Schedule	97
Forecasted Sustainment Requirement	98
Deficiency Summary By System	99
Deficiency Summary By Priority	100

Campus Assessment Report

Deficiency By Priority Investment	101
Deficiency Summary By Category	102
Deficiency Details By Priority	103

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	37,897
Year Built:	1957
Last Renovation:	
Replacement Value:	\$8,448,918
Repair Cost:	\$2,264,040.00
Total FCI:	26.80 %
Total RSLI:	28.82 %
FCA Score:	73.20



Description:

GENERAL:

Wayne Avenue Elementary is located at 910 W Harnett Street in Dunn, North Carolina. The 1 story, 27,822 square foot building was originally constructed in 1957 There have been 2 additions. A Media Center and Multi-Purpose room was added between 1998 and 2005. In addition to the main building, the campus contains 10 mobile classes.

This report contains condition and adequacy data collected during the 2016 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

The building rests on slab-on grade and is assumed to have standard cast-in-place concrete foundations. The building does not have a basement.

Campus Assessment Report - Wayne Avenue Elementary

B. SUPERSTRUCTURE

Roof construction is steel. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with fixed panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is typically low slope single ply membrane. Most building entrances appear to comply with ADA requirements.

C. INTERIORS

Interior partitions are typically CMU. Interior doors are generally solid core wood with wood frames and mostly with glazing. Interior fittings include the following items: white boards, toilet accessories, storage shelving, handrails, and fabricated toilet partitions. The interior wall finishes are typically painted CMU. Floor finishes in common areas are typically vinyl composition tile. Floor finishes in assignable spaces is typically carpet. Ceiling finishes in common areas are typically 1X1 glue on acoustical tile, painted hard lid and suspended acoustical tile.

CONVEYING:

The building does not include conveying equipment.

D. SERVICES

PLUMBING: Plumbing fixtures are typically on-low-flow water fixtures with manual control valves. Domestic water distribution is combination of copper and galvanized steel with electric hot water heating. Sanitary waste system is cast iron. Rain water drainage system is internal with roof drains. Other plumbing systems is supplied by natural gas.

HVAC:

Heating and Cooling is supplied by AC/Heat combo units. Ceiling mounted exhaust fans are installed in bathrooms and other required areas.

FIRE PROTECTION:

The building does not have a fire sprinkler system. The building does have additional fire suppression systems, which include dry chemical system for the kitchen exhaust hood. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in, recessed and surface type, fluorescent light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in common spaces, balconies and interior corridors. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building includes an internal security system that is actuated by the following items: contacts, infrared, optical or a combination of all devices. The security system has CCTV cameras and is centrally monitored; this building has a public address and paging system separate from the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does not have a separately derived emergency power system.

E. EQUIPMENT & FURNISHINGS:

This building includes the following items and equipment: fixed food service, library equipment, athletic equipment, theater and stage, audio-visual, laboratory, casework, window treatment, floor grilles and mats, and multiple seating furnishings.

G. SITE:

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting.

Campus Assessment Report - Wayne Avenue Elementary

Attributes:

General Attributes:





Condition Assessor:	Terence Davis	Assessment Date:	11/15/2016
Suitability Assessor:			

School Information:

HS Attendance Area:	Harnett - Triton HS	LEA School No.:	430-380
No. of Mobile Units:	10	No. of Bldgs.:	3
SF of Mobile Units:	8448	Status:	Active
School Grades:	4-5	Site Acreage:	7.6

Campus Dashboard Summary

Gross Area:	37,897	Last Renovation:	
Year Built:	1957	Replacement Value:	\$8,448,918
Repair Cost:	\$2,264,040	RSLI%:	28.82 %
FCI:	26.80 %		



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	51.38 %	0.00 %	\$0.00
A20 - Basement Construction	51.38 %	0.00 %	\$0.00
B10 - Superstructure	51.38 %	0.00 %	\$0.00
B20 - Exterior Enclosure	30.27 %	41.96 %	\$287,373.00
B30 - Roofing	14.17 %	99.82 %	\$300,171.00
C10 - Interior Construction	26.48 %	0.00 %	\$0.00
C30 - Interior Finishes	22.04 %	8.98 %	\$85,386.00
D20 - Plumbing	11.72 %	80.24 %	\$428,458.00
D30 - HVAC	8.22 %	80.76 %	\$609,329.00
D40 - Fire Protection	11.53 %	80.95 %	\$152,715.00
D50 - Electrical	41.41 %	14.46 %	\$154,857.00
E10 - Equipment	3.46 %	97.57 %	\$67,329.00
E20 - Furnishings	1.00 %	87.93 %	\$178,422.00
G20 - Site Improvements	16.86 %	0.00 %	\$0.00
G30 - Site Mechanical Utilities	24.05 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	47.64 %	0.00 %	\$0.00
Totals:	28.82 %	26.80 %	\$2,264,040.00

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
1957 Main	27,822	41.44	\$0.00	\$0.00	\$2,111,325.00	\$152,715.00	\$0.00
1998 Media Center	6,983	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2005 Multi Purpose Room	3,092	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Site	37,897	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Total:		26.80	\$0.00	\$0.00	\$2,111,325.00	\$152,715.00	\$0.00

Deficiencies By Priority



- 1 - Currently Critical (Immediate)
- 2 - Potentially Critical (Year 1)
- 3 - Necessary/Not Yet Critical (Years 2-5) - \$2,111,325.00
- 4 - Recommended (Years 6-10) - \$152,715.00
- 5 - Codes or Standards Compliance

Budget Estimate Total: \$2,264,040.00

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	27,822
Year Built:	1957
Last Renovation:	
Replacement Value:	\$5,462,851
Repair Cost:	\$2,264,040.00
Total FCI:	41.44 %
Total RSLI:	22.32 %
FCA Score:	58.56







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	27,822
Year Built:	1957	Last Renovation:	
Repair Cost:	\$2,264,040	Replacement Value:	\$5,462,851
FCI:	41.44 %	RSLI%:	22.32 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	40.00 %	0.00 %	\$0.00
A20 - Basement Construction	40.00 %	0.00 %	\$0.00
B10 - Superstructure	40.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	19.51 %	52.04 %	\$287,373.00
B30 - Roofing	0.00 %	148.40 %	\$300,171.00
C10 - Interior Construction	18.90 %	0.00 %	\$0.00
C30 - Interior Finishes	20.75 %	12.21 %	\$85,386.00
D20 - Plumbing	0.39 %	108.68 %	\$428,458.00
D30 - HVAC	0.00 %	110.00 %	\$609,329.00
D40 - Fire Protection	0.00 %	110.00 %	\$152,715.00
D50 - Electrical	42.62 %	19.65 %	\$154,857.00
E10 - Equipment	0.00 %	110.00 %	\$67,329.00
E20 - Furnishings	0.00 %	110.00 %	\$178,422.00
Totals:	22.32 %	41.44 %	\$2,264,040.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Dec 08, 2016



2). East Elevation - Dec 08, 2016



3). North Elevation - Dec 08, 2016



4). West Elevation - Dec 08, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

Campus Assessment Report - 1957 Main

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.79	S.F.	27,822	100	1957	2057		40.00 %	0.00 %	40			\$133,267
A1030	Slab on Grade	\$8.43	S.F.	27,822	100	1957	2057		40.00 %	0.00 %	40			\$234,539
A2010	Basement Excavation	\$1.90	S.F.	27,822	100	1957	2057		40.00 %	0.00 %	40			\$52,862
A2020	Basement Walls	\$13.07	S.F.	27,822	100	1957	2057		40.00 %	0.00 %	40			\$363,634
B1010	Floor Construction	\$1.64	S.F.	27,822	100	1957	2057		40.00 %	0.00 %	40			\$45,628
B1020	Roof Construction	\$15.76	S.F.	27,822	100	1957	2057		40.00 %	0.00 %	40			\$438,475
B2010	Exterior Walls	\$9.42	S.F.	27,822	100	1957	2057		40.00 %	0.00 %	40			\$262,083
B2020	Exterior Windows	\$9.39	S.F.	27,822	30	1957	1987		0.00 %	110.00 %	-30		\$287,373.00	\$261,249
B2030	Exterior Doors	\$1.04	S.F.	27,822	30	1990	2020		10.00 %	0.00 %	3			\$28,935
B3010120	Single Ply Membrane	\$6.98	S.F.	27,822	20	1957	1977		0.00 %	150.00 %	-40		\$291,296.00	\$194,198
B3020	Roof Openings	\$0.29	S.F.	27,822	25	1957	1982		0.00 %	110.00 %	-35		\$8,875.00	\$8,068
C1010	Partitions	\$10.80	S.F.	27,822	75	1957	2032		20.00 %	0.00 %	15			\$300,478
C1020	Interior Doors	\$2.53	S.F.	27,822	30	1990	2020		10.00 %	0.00 %	3			\$70,390
C1030	Fittings	\$9.74	S.F.	27,822	20	1957	1977	2021	20.00 %	0.00 %	4			\$270,986
C3010	Wall Finishes	\$2.79	S.F.	27,822	10	2000	2010		0.00 %	110.00 %	-7		\$85,386.00	\$77,623
C3020	Floor Finishes	\$11.38	S.F.	27,822	20	2000	2020		15.00 %	0.00 %	3			\$316,614
C3030	Ceiling Finishes	\$10.97	S.F.	27,822	25	2000	2025		32.00 %	0.00 %	8			\$305,207
D2010	Plumbing Fixtures	\$11.48	S.F.	27,822	30	1980	2010		0.00 %	110.00 %	-7		\$351,336.00	\$319,397
D2020	Domestic Water Distribution	\$0.98	S.F.	27,822	30	1957	1987		0.00 %	110.00 %	-30		\$29,992.00	\$27,266
D2030	Sanitary Waste	\$1.54	S.F.	27,822	30	1957	1987		0.00 %	110.00 %	-30		\$47,130.00	\$42,846
D2090	Other Plumbing Systems -Nat Gas	\$0.17	S.F.	27,822	40	1990	2030		32.50 %	0.00 %	13			\$4,730
D3040	Distribution Systems	\$6.26	S.F.	27,822	30	1957	1987		0.00 %	110.00 %	-30		\$191,582.00	\$174,166
D3050	Terminal & Package Units	\$13.65	S.F.	27,822	15	2000	2015		0.00 %	110.00 %	-2		\$417,747.00	\$379,770
D4010	Sprinklers	\$4.32	S.F.	27,822	30			2016	0.00 %	110.00 %	-1		\$132,210.00	\$120,191
D4020	Standpipes	\$0.67	S.F.	27,822	30			2016	0.00 %	110.00 %	-1		\$20,505.00	\$18,641
D5010	Electrical Service/Distribution	\$1.69	S.F.	27,822	40	1980	2020		7.50 %	0.00 %	3			\$47,019
D5020	Branch Wiring	\$5.06	S.F.	27,822	30	1980	2010		0.00 %	110.00 %	-7		\$154,857.00	\$140,779
D5020	Lighting	\$11.92	S.F.	27,822	30	1996	2026		30.00 %	0.00 %	9			\$331,638
D5030810	Security & Detection Systems	\$1.87	S.F.	27,822	15	2015	2030		86.67 %	0.00 %	13			\$52,027
D5030910	Fire Alarm Systems	\$3.39	S.F.	27,822	15	2015	2030		86.67 %	0.00 %	13			\$94,317
D5030920	Data Communication	\$4.40	S.F.	27,822	15	2015	2030		86.67 %	0.00 %	13			\$122,417
E1020	Institutional Equipment	\$0.30	S.F.	27,822	20	1990	2010		0.00 %	109.99 %	-7		\$9,181.00	\$8,347
E1090	Other Equipment	\$1.90	S.F.	27,822	20	1990	2010		0.00 %	110.00 %	-7		\$58,148.00	\$52,862
E2010	Fixed Furnishings	\$5.83	S.F.	27,822	20	1990	2010		0.00 %	110.00 %	-7		\$178,422.00	\$162,202
Total									22.32 %	41.44 %			\$2,264,040.00	\$5,462,851

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1957 Main

System: B3010120 - Single Ply Membrane



Note:

System: B3020 - Roof Openings



Note:


System: C1010 - Partitions



Note:

Campus Assessment Report - 1957 Main

System: C1020 - Interior Doors




Note:

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:


Campus Assessment Report - 1957 Main

System: C3020 - Floor Finishes





Note:

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

Campus Assessment Report - 1957 Main

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D2090 - Other Plumbing Systems -Nat Gas



Note:

Campus Assessment Report - 1957 Main

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:

System: D5010 - Electrical Service/Distribution



Note:

Campus Assessment Report - 1957 Main

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:

Campus Assessment Report - 1957 Main

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

System: E1020 - Institutional Equipment



Note:

Campus Assessment Report - 1957 Main

System: E1090 - Other Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$2,264,040	\$0	\$0	\$556,476	\$335,497	\$0	\$0	\$0	\$425,290	\$475,984	\$114,752	\$4,172,039
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$287,373	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$287,373
B2030 - Exterior Doors	\$0	\$0	\$0	\$34,779	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,779
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$291,296	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$291,296
B3020 - Roof Openings	\$8,875	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,875
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$84,609	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$84,609
C1030 - Fittings	\$0	\$0	\$0	\$0	\$335,497	\$0	\$0	\$0	\$0	\$0	\$0	\$335,497
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1957 Main

C3010 - Wall Finishes	\$85,386	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$114,752	\$200,138
C3020 - Floor Finishes	\$0	\$0	\$0	\$380,571	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$380,571
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$425,290	\$0	\$0	\$425,290
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$351,336	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$351,336
D2020 - Domestic Water Distribution	\$29,992	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$29,992
D2030 - Sanitary Waste	\$47,130	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$47,130
D2090 - Other Plumbing Systems -Nat Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$191,582	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$191,582
D3050 - Terminal & Package Units	\$417,747	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$417,747
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$132,210	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$132,210
D4020 - Standpipes	\$20,505	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$20,505
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$56,517	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$56,517
D5020 - Branch Wiring	\$154,857	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$154,857
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$475,984	\$0	\$475,984
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$9,181	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$9,181
E1090 - Other Equipment	\$58,148	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$58,148
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$178,422	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$178,422

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$2,264,040.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$2,264,040.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2020	Exterior Windows	\$0.00	\$0.00	\$287,373.00	\$0.00	\$0.00	\$287,373.00
B3010120	Single Ply Membrane	\$0.00	\$0.00	\$291,296.00	\$0.00	\$0.00	\$291,296.00
B3020	Roof Openings	\$0.00	\$0.00	\$8,875.00	\$0.00	\$0.00	\$8,875.00
C3010	Wall Finishes	\$0.00	\$0.00	\$85,386.00	\$0.00	\$0.00	\$85,386.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$351,336.00	\$0.00	\$0.00	\$351,336.00
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$29,992.00	\$0.00	\$0.00	\$29,992.00
D2030	Sanitary Waste	\$0.00	\$0.00	\$47,130.00	\$0.00	\$0.00	\$47,130.00
D3040	Distribution Systems	\$0.00	\$0.00	\$191,582.00	\$0.00	\$0.00	\$191,582.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$417,747.00	\$0.00	\$0.00	\$417,747.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$132,210.00	\$0.00	\$132,210.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$20,505.00	\$0.00	\$20,505.00
D5020	Branch Wiring	\$0.00	\$0.00	\$154,857.00	\$0.00	\$0.00	\$154,857.00
E1020	Institutional Equipment	\$0.00	\$0.00	\$9,181.00	\$0.00	\$0.00	\$9,181.00
E1090	Other Equipment	\$0.00	\$0.00	\$58,148.00	\$0.00	\$0.00	\$58,148.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$178,422.00	\$0.00	\$0.00	\$178,422.00
	Total:	\$0.00	\$0.00	\$2,111,325.00	\$152,715.00	\$0.00	\$2,264,040.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2020 - Exterior Windows



Location: Exterior
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$287,373.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: The aluminum frame single pane windows are aged, rusted, not energy efficient, and should be replaced.

System: B3010120 - Single Ply Membrane



Location: Roof
Distress: Failing
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$291,296.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: The single ply adhered roof coverings are aging, showing signs of failure and should be replaced.

System: B3020 - Roof Openings



Location: Roof
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$8,875.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: The roof openings should be inspected and repaired when the roof is replaced.

System: C3010 - Wall Finishes



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$85,386.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: The wall finishes are aged, scuffed, fading, stained, and should be re-painted.

System: D2010 - Plumbing Fixtures



Location: Restroom
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$351,336.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: Plumbing fixtures are in operational conditions. However, they are aged, not ADA compliant and should be replaced with a low-flow water fixtures.

System: D2020 - Domestic Water Distribution



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$29,992.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: There are no reported issues or observed deficiencies with the domestic water piping. Due to the age of the pipe there can be internal pitting corrosion that may be a costly problem that leads to the formation of pinhole leaks and possible water contamination.

System: D2030 - Sanitary Waste



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$47,130.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: The sanitary waste system is aged and should be replaced.

System: D3040 - Distribution Systems



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$191,582.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: The distribution system is aged, in marginal condition, and should be replaced.

System: D3050 - Terminal & Package Units



Location: Exterior
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$417,747.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: The wall mounted Carrier DX condensing units are aged and should be scheduled for replacement.

System: D5020 - Branch Wiring



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$154,857.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: The original electrical service is operating, maxed to capacity and should be replaced.

System: E1020 - Institutional Equipment



Location: kitchen
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$9,181.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: The Library Equipment, Theater Stage Equipment, Audio-visual Equipment, Other Institutional Equipment is operating but is aged, becoming logistically un-supportable, and should be replaced.


System: E1090 - Other Equipment



Location: Kitchen
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$58,148.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: The Food Service Equipment is operating but is aged should be inspected and replaced or repaired as needed.

System: E2010 - Fixed Furnishings



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$178,422.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: The fixed furnishings are aged, in marginal condition, and should be replaced.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$132,210.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: There is no sprinkler system in the building.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 27,822.00
Unit of Measure: S.F.
Estimate: \$20,505.00
Assessor Name: Terence Davis
Date Created: 12/08/2016

Notes: There is no sprinkler system in the building.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	6,983
Year Built:	1998
Last Renovation:	
Replacement Value:	\$1,307,010
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	45.48 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.


Dashboard Summary

Function:	ES -Elementary School	Gross Area:	6,983
Year Built:	1998	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$1,307,010
FCI:	0.00 %	RSLI%:	45.48 %

No data found for this asset

No data found for this asset

No data found for this asset



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	81.00 %	0.00 %	\$0.00
A20 - Basement Construction	81.00 %	0.00 %	\$0.00
B10 - Superstructure	81.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	76.59 %	0.00 %	\$0.00
B30 - Roofing	36.30 %	0.00 %	\$0.00
C10 - Interior Construction	41.09 %	0.00 %	\$0.00
C30 - Interior Finishes	17.18 %	0.00 %	\$0.00
D20 - Plumbing	36.67 %	0.00 %	\$0.00
D30 - HVAC	29.81 %	0.00 %	\$0.00
D40 - Fire Protection	36.67 %	0.00 %	\$0.00
D50 - Electrical	34.20 %	0.00 %	\$0.00
E10 - Equipment	5.00 %	0.00 %	\$0.00
E20 - Furnishings	5.00 %	0.00 %	\$0.00
Totals:	45.48 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). West Elevation - Dec 08, 2016



2). West Elevation - Dec 08, 2016



3). South Elevation - Dec 08, 2016



4). East Elevation - Dec 08, 2016



5). North Elevation - Dec 08, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.79	S.F.	6,983	100	1998	2098		81.00 %	0.00 %	81			\$33,449
A1030	Slab on Grade	\$8.43	S.F.	6,983	100	1998	2098		81.00 %	0.00 %	81			\$58,867
A2010	Basement Excavation	\$1.90	S.F.	6,983	100	1998	2098		81.00 %	0.00 %	81			\$13,268
A2020	Basement Walls	\$13.07	S.F.	6,983	100	1998	2098		81.00 %	0.00 %	81			\$91,268
B1010	Floor Construction	\$1.64	S.F.	6,983	100	1998	2098		81.00 %	0.00 %	81			\$11,452
B1020	Roof Construction	\$15.76	S.F.	6,983	100	1998	2098		81.00 %	0.00 %	81			\$110,052
B2010	Exterior Walls	\$9.42	S.F.	6,983	100	1998	2098		81.00 %	0.00 %	81			\$65,780
B2030	Exterior Doors	\$1.04	S.F.	6,983	30	1998	2028		36.67 %	0.00 %	11			\$7,262
B3010130	Preformed Metal Roofing	\$9.66	S.F.	6,983	30	1998	2028		36.67 %	0.00 %	11			\$67,456
B3020	Roof Openings	\$0.29	S.F.	6,983	25	1998	2023		24.00 %	0.00 %	6			\$2,025
C1010	Partitions	\$10.80	S.F.	6,983	75	1998	2073		74.67 %	0.00 %	56			\$75,416
C1020	Interior Doors	\$2.53	S.F.	6,983	30	1998	2028		36.67 %	0.00 %	11			\$17,667
C1030	Fittings	\$9.74	S.F.	6,983	20	1998	2018		5.00 %	0.00 %	1			\$68,014
C3010	Wall Finishes	\$2.79	S.F.	6,983	10	1998	2008	2021	40.00 %	0.00 %	4			\$19,483
C3020	Floor Finishes	\$11.38	S.F.	6,983	20	1998	2018		5.00 %	0.00 %	1			\$79,467
C3030	Ceiling Finishes	\$10.97	S.F.	6,983	25	1998	2023		24.00 %	0.00 %	6			\$76,604
D2010	Plumbing Fixtures	\$11.48	S.F.	6,983	30	1998	2028		36.67 %	0.00 %	11			\$80,165
D2020	Domestic Water Distribution	\$0.98	S.F.	6,983	30	1998	2028		36.67 %	0.00 %	11			\$6,843
D2030	Sanitary Waste	\$1.54	S.F.	6,983	30	1998	2028		36.67 %	0.00 %	11			\$10,754
D3040	Distribution Systems	\$6.14	S.F.	6,983	30	1998	2028		36.67 %	0.00 %	11			\$42,876
D3050	Terminal & Package Units	\$13.37	S.F.	6,983	15	1998	2013	2021	26.67 %	0.00 %	4			\$93,363
D4010	Sprinklers	\$4.32	S.F.	6,983	30	1998	2028		36.67 %	0.00 %	11			\$30,167
D4020	Standpipes	\$0.67	S.F.	6,983	30	1998	2028		36.67 %	0.00 %	11			\$4,679
D5010	Electrical Service/Distribution	\$1.69	S.F.	6,983	40	1998	2038		52.50 %	0.00 %	21			\$11,801
D5020	Branch Wiring	\$5.06	S.F.	6,983	30	1998	2028		36.67 %	0.00 %	11			\$35,334
D5020	Lighting	\$11.92	S.F.	6,983	30	1998	2028		36.67 %	0.00 %	11			\$83,237
D5030810	Security & Detection Systems	\$1.87	S.F.	6,983	15	1998	2013	2021	26.67 %	0.00 %	4			\$13,058
D5030910	Fire Alarm Systems	\$3.39	S.F.	6,983	15	1998	2013	2021	26.67 %	0.00 %	4			\$23,672
D5030920	Data Communication	\$4.40	S.F.	6,983	15	1998	2013	2021	26.67 %	0.00 %	4			\$30,725
E1020	Institutional Equipment	\$0.30	S.F.	6,983	20	1998	2018		5.00 %	0.00 %	1			\$2,095
E2010	Fixed Furnishings	\$5.83	S.F.	6,983	20	1998	2018		5.00 %	0.00 %	1			\$40,711
Total									45.48 %					\$1,307,010

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2030 - Exterior Doors



Note:

System: B3010130 - Preformed Metal Roofing



Note:




Campus Assessment Report - 1998 Media Center

System: B3020 - Roof Openings



Note:

System: C1010 - Partitions



Note:



System: C1020 - Interior Doors



Note:


Campus Assessment Report - 1998 Media Center

System: C1030 - Fittings




Note:

System: C3010 - Wall Finishes



Note:


System: C3020 - Floor Finishes



Note:

Campus Assessment Report - 1998 Media Center

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

Campus Assessment Report - 1998 Media Center

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:


Campus Assessment Report - 1998 Media Center

System: D5010 - Electrical Service/Distribution




Note:

System: D5020 - Branch Wiring



Note:


System: D5020 - Lighting



Note:

Campus Assessment Report - 1998 Media Center

System: D5030810 - Security & Detection Systems



Note:

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

Campus Assessment Report - 1998 Media Center

System: E1020 - Institutional Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$215,594	\$0	\$0	\$223,224	\$0	\$103,276	\$0	\$0	\$0	\$0	\$542,095
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$2,660	\$0	\$0	\$0	\$0	\$2,660
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$77,060	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$77,060
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$24,121	\$0	\$0	\$0	\$0	\$0	\$0	\$24,121


Campus Assessment Report - 1998 Media Center

C3020 - Floor Finishes	\$0	\$90,035	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$90,035
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$100,616	\$0	\$0	\$0	\$0	\$0	\$100,616
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$115,589	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$115,589
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$16,167	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$16,167
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$29,308	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$29,308
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$38,040	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$38,040
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$2,373	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,373
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$46,125	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$46,125

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	3,092
Year Built:	2005
Last Renovation:	
Replacement Value:	\$581,940
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	61.30 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.


Dashboard Summary

Function:	ES -Elementary School	Gross Area:	3,092
Year Built:	2005	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$581,940
FCI:	0.00 %	RSLI%:	61.30 %

No data found for this asset

No data found for this asset

No data found for this asset



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	88.00 %	0.00 %	\$0.00
A20 - Basement Construction	88.00 %	0.00 %	\$0.00
B10 - Superstructure	88.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	73.29 %	0.00 %	\$0.00
B30 - Roofing	60.00 %	0.00 %	\$0.00
C10 - Interior Construction	62.79 %	0.00 %	\$0.00
C30 - Interior Finishes	45.24 %	0.00 %	\$0.00
D20 - Plumbing	60.00 %	0.00 %	\$0.00
D30 - HVAC	33.26 %	0.00 %	\$0.00
D40 - Fire Protection	60.00 %	0.00 %	\$0.00
D50 - Electrical	46.96 %	0.00 %	\$0.00
E10 - Equipment	40.00 %	0.00 %	\$0.00
Totals:	61.30 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Dec 08, 2016



2). West Elevation - Dec 08, 2016



3). Nort Elevation - Dec 08, 2016



4). East Elevation - Dec 08, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

Campus Assessment Report - 2005 Multi Purpose Room

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.79	S.F.	3,000	100	2005	2105		88.00 %	0.00 %	88			\$14,370
A1030	Slab on Grade	\$8.43	S.F.	3,000	100	2005	2105		88.00 %	0.00 %	88			\$25,290
A2010	Basement Excavation	\$1.90	S.F.	3,000	100	2005	2105		88.00 %	0.00 %	88			\$5,700
A2020	Basement Walls	\$13.07	S.F.	3,000	100	2005	2105		88.00 %	0.00 %	88			\$39,210
B1010	Floor Construction	\$1.64	S.F.	3,000	100	2005	2105		88.00 %	0.00 %	88			\$4,920
B1020	Roof Construction	\$15.76	S.F.	3,000	100	2005	2105		88.00 %	0.00 %	88			\$47,280
B2010	Exterior Walls	\$9.42	S.F.	3,000	100	2005	2105		88.00 %	0.00 %	88			\$28,260
B2020	Exterior Windows	\$9.39	S.F.	3,000	30	2005	2035		60.00 %	0.00 %	18			\$28,170
B2030	Exterior Doors	\$1.04	S.F.	3,000	30	2005	2035		60.00 %	0.00 %	18			\$3,120
B3010130	Preformed Metal Roofing	\$9.66	S.F.	3,000	30	2005	2035		60.00 %	0.00 %	18			\$28,980
C1010	Partitions	\$10.80	S.F.	3,000	75	2005	2080		84.00 %	0.00 %	63			\$32,400
C1020	Interior Doors	\$2.53	S.F.	3,000	30	2005	2035		60.00 %	0.00 %	18			\$7,590
C1030	Fittings	\$9.74	S.F.	3,000	20	2005	2025		40.00 %	0.00 %	8			\$29,220
C3010	Wall Finishes	\$2.79	S.F.	3,000	10	2005	2015	2021	40.00 %	0.00 %	4			\$8,370
C3020	Floor Finishes	\$11.38	S.F.	3,000	20	2005	2025		40.00 %	0.00 %	8			\$34,140
C3030	Ceiling Finishes	\$10.97	S.F.	3,000	25	2005	2030		52.00 %	0.00 %	13			\$32,910
D2010	Plumbing Fixtures	\$11.48	S.F.	3,000	30	2005	2035		60.00 %	0.00 %	18			\$34,440
D2020	Domestic Water Distribution	\$0.98	S.F.	3,000	30	2005	2035		60.00 %	0.00 %	18			\$2,940
D2030	Sanitary Waste	\$1.54	S.F.	3,000	30	2005	2035		60.00 %	0.00 %	18			\$4,620
D3040	Distribution Systems	\$6.14	S.F.	3,000	30	2005	2035		60.00 %	0.00 %	18			\$18,420
D3050	Terminal & Package Units	\$13.37	S.F.	3,000	15	2005	2020		20.00 %	0.00 %	3			\$40,110
D3060	Controls & Instrumentation	\$1.94	S.F.	3,000	20	2005	2025		40.00 %	0.00 %	8			\$5,820
D4010	Sprinklers	\$4.32	S.F.	3,000	30	2005	2035		60.00 %	0.00 %	18			\$12,960
D4020	Standpipes	\$0.67	S.F.	3,000	30	2005	2035		60.00 %	0.00 %	18			\$2,010
D5010	Electrical Service/Distribution	\$1.69	S.F.	3,000	40	2005	2045		70.00 %	0.00 %	28			\$5,070
D5020	Branch Wiring	\$5.06	S.F.	3,000	30	2005	2035		60.00 %	0.00 %	18			\$15,180
D5020	Lighting	\$11.92	S.F.	3,000	30	2005	2035		60.00 %	0.00 %	18			\$35,760
D5030810	Security & Detection Systems	\$1.87	S.F.	3,000	15	2005	2020		20.00 %	0.00 %	3			\$5,610
D5030910	Fire Alarm Systems	\$3.39	S.F.	3,000	15	2005	2020		20.00 %	0.00 %	3			\$10,170
D5030920	Data Communication	\$4.40	S.F.	3,000	15	2005	2020		20.00 %	0.00 %	3			\$13,200
E1090	Other Equipment	\$1.90	S.F.	3,000	20	2005	2025		40.00 %	0.00 %	8			\$5,700
Total									61.30 %					\$581,940

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:


System: B2020 - Exterior Windows



Note:

Campus Assessment Report - 2005 Multi Purpose Room

System: B2030 - Exterior Doors






Note:

System: B3010130 - Preformed Metal Roofing



Note:


System: C1010 - Partitions



Note:

Campus Assessment Report - 2005 Multi Purpose Room

System: C1020 - Interior Doors




Note:

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:


Campus Assessment Report - 2005 Multi Purpose Room

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

Campus Assessment Report - 2005 Multi Purpose Room

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:

Campus Assessment Report - 2005 Multi Purpose Room

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:

System: D5010 - Electrical Service/Distribution



Note:


Campus Assessment Report - 2005 Multi Purpose Room

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:


Campus Assessment Report - 2005 Multi Purpose Room

System: D5030910 - Fire Alarm Systems




Note:

System: D5030920 - Data Communication



Note:

System: E1090 - Other Equipment



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$0	\$83,046	\$10,363	\$0	\$0	\$0	\$104,341	\$0	\$0	\$197,750
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$40,717	\$0	\$0	\$40,717
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$10,363	\$0	\$0	\$0	\$0	\$0	\$0	\$10,363


Campus Assessment Report - 2005 Multi Purpose Room

C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$47,572	\$0	\$0	\$47,572
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$48,212	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$48,212
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,110	\$0	\$0	\$8,110
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$6,743	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,743
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$12,224	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$12,224
D5030920 - Data Communication	\$0	\$0	\$0	\$15,866	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$15,866
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$7,943	\$0	\$0	\$7,943

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	37,897
Year Built:	1957
Last Renovation:	
Replacement Value:	\$1,097,117
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	24.13 %
FCA Score:	100.00



Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.


Dashboard Summary

Function:	ES -Elementary School	Gross Area:	37,897
Year Built:	1957	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$1,097,117
FCI:	0.00 %	RSLI%:	24.13 %

No data found for this asset

No data found for this asset

No data found for this asset



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	16.86 %	0.00 %	\$0.00
G30 - Site Mechanical Utilities	24.05 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	47.64 %	0.00 %	\$0.00
Totals:	24.13 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

- 1). Aerial Image of Wayne Avenue Elementary School - Mar 03, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$3.81	S.F.	37,897	25	1998	2023		24.00 %	0.00 %	6			\$144,388
G2020	Parking Lots	\$1.33	S.F.	37,897	25	1998	2023		24.00 %	0.00 %	6			\$50,403
G2030	Pedestrian Paving	\$1.91	S.F.	37,897	30	1998	2028		36.67 %	0.00 %	11			\$72,383
G2040950	Covered Walkways	\$1.52	S.F.	37,897	25	1998	2023		24.00 %	0.00 %	6			\$57,603
G2040950	Playing Field	\$4.54	S.F.	37,897	20	1998	2018		5.00 %	0.00 %	1			\$172,052
G2050	Landscaping	\$1.87	S.F.	37,897	15	1998	2013		0.00 %	0.00 %	-4			\$70,867
G3010	Water Supply	\$2.34	S.F.	37,897	50	1980	2030		26.00 %	0.00 %	13			\$88,679
G3020	Sanitary Sewer	\$1.45	S.F.	37,897	50	1980	2030		26.00 %	0.00 %	13			\$54,951
G3030	Storm Sewer	\$4.54	S.F.	37,897	50	1980	2030		26.00 %	0.00 %	13			\$172,052
G3060	Fuel Distribution	\$0.98	S.F.	37,897	40	1980	2020		7.50 %	0.00 %	3			\$37,139
G4010	Electrical Distribution	\$2.35	S.F.	37,897	50	1998	2048		62.00 %	0.00 %	31			\$89,058
G4020	Site Lighting	\$1.47	S.F.	37,897	30	1998	2028		36.67 %	0.00 %	11			\$55,709
G4030	Site Communications & Security	\$0.84	S.F.	37,897	15	1998	2013	2021	26.67 %	0.00 %	4			\$31,833
Total									24.13 %					\$1,097,117

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways



Note:

System: G2020 - Parking Lots



Note:

System: G2030 - Pedestrian Paving



Note:

Campus Assessment Report - Site

System: G2040950 - Covered Walkways



Note:

System: G2040950 - Playing Field



Note:

System: G2050 - Landscaping



Note:

Campus Assessment Report - Site

System: G3010 - Water Supply



Note:

System: G3020 - Sanitary Sewer



Note:

System: G3030 - Storm Sewer



Note:

Campus Assessment Report - Site

System: G3060 - Fuel Distribution




Note:

System: G4010 - Electrical Distribution



Note:

System: G4020 - Site Lighting



Note:

Campus Assessment Report - Site

System: G4030 - Site Communications & Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$194,936	\$0	\$44,641	\$39,412	\$0	\$331,508	\$0	\$0	\$0	\$0	\$610,497
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$189,647	\$0	\$0	\$0	\$0	\$189,647
G2020 - Parking Lots	\$0	\$0	\$0	\$0	\$0	\$0	\$66,202	\$0	\$0	\$0	\$0	\$66,202
G2030 - Pedestrian Paving	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040950 - Covered Walkways	\$0	\$0	\$0	\$0	\$0	\$0	\$75,660	\$0	\$0	\$0	\$0	\$75,660
G2040950 - Playing Field	\$0	\$194,936	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$194,936
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3060 - Fuel Distribution	\$0	\$0	\$0	\$44,641	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$44,641
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$39,412	\$0	\$0	\$0	\$0	\$0	\$0	\$39,412

** Indicates non-renewable system*

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset